

CHAINS

RESTORED FOR OREGON STATE BOARD OF FORESTRY

Corner common to sections 3, 4, 33, 34, T. 1 & 2 N., R. 7 W.,
W.M., Tillamook County, Oregon.

ORIGINAL

Post; now missing, from which a:

28" Hemlock bears N39E 73 lks; now 33" snag both faces
exposed and badly burnt; scribe mark T barely visible
on lower face.

10" Hemlock bears N61W 81 lks; now missing.

10" Hemlock bears S42E 43lks; now down 12" stub badly
charred and out of place. Parts of the roots of
this stub were found in place attached to a 5' fir
stump; exposed scribe mark T.

4" Maple bears S9W 51 lks; now missing.

RESTORED CORNER AND BEARING TREES

Set 1½" x 36" galvanized iron pipe with 3" bronze cap marked
"OREGON STATE BOARD OF FORESTRY T2N R7W S33 S34 S4 S3 T1N
1952 2311", 2½" in ground, from which a:

6' Fir stump bears N75°30'W 34.6'; scribed T2N R7W S33
BT 2311.

5' Fir stump bears N35E 89.3'; scribed T2N R7W S34 BT 2311.


5' Fir stump bears S10E 69.3'; scribed T1N R7W S3 BT.

Placed an Oregon State Board of Forestry metal location poster
on 33" Hemlock snag BT and marked it: Sec 34 T2N R7W
Sec Cor 48.2' S39W.

Pipe is set under 4' fir log with X chopped in log above corner
point.

Dated February 26, 1952.

This corner was restored by Don D. Davis
Don D. Davis Asst. Forest Engineer
under my direction.



Present and witnessed by Richard A. Morris
Richard A. Morris Compassman