

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

Section corner common to sections 25, 30, 31, and 36, T2S R6 and 7W, WM., Tillamook County, Oregon.

ORIGINAL

Post, now missing, from which a:

- 13" Hemlock bears S40W 115 lks; now 32" stub 7" high, cast of scribe marks BT exposed.
- 12" Hemlock bears N80W 40 lks, now missing.
- 20" Hemlock bears S45E 34 lks, now 20" down snag, exposed scribe marks T R8.
- 10" Hemlock bears N70E 8 lks, now missing.

At the corner point, found 1/2" iron pipe with 2" bronze cap stamped LHL LBR. CORP. T2S 25 30 36 31 R7W R6W 1951.

RESTORED BEARING TREES


Raised mound of stone around corner pipe, from which a:

- 60" Fir stump bears N39E 62.2'; scribed T2S R6W S30 BT RE 2311.
- 42" Fir stump bears N64°30'W 37.5'; scribed T2S R7W S25 BT.
- 49" Fir stump bears S56W 65.5'; scribed T2S R7W S36 BT.
- 66" Fir stump bears S54E 73.6'; scribed T2S R6W S31 BT.

Placed an Oregon State Board of Forestry metal location poster on 42" Fir stump and marked it: Sec 25 T2S R7W 37.5 Ft. S64°30'E.

Dated August 15, 1952.

This corner was restored by Don D. Davis, under my direction. Don D. Davis Assistant Forest Engineer



Present and witnessed by Richard A. Morris Richard A. Morris Compassman

Present and witnessed by Robert A. Young Robert A. Young Chainman