

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

Section corner common to sections 1, 2, 11, and 12, T3S R7W, W1., Tillamook County, Oregon.

ORIGINAL

Post, now missing, from which a:

- 40" Fir bears N32W 42 lks; now 60" stump, did not attempt to expose scribe marks.
- 15" Hemlock bears N22E 69 lks, now 32" stump, scribe marks T W exposed.
- 16" Hemlock bears S64E 118 lks, now root stub.
- 18" Hemlock bears S40W 57 lks, now 24" stub 7' high, badly burned.

RESTORED CORNER AND BEARING TREES


Set 1 1/2" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY T3S R7W S2 S1 S11 S12 1952 2311," 2 1/2' in ground, from which a:

- 51" Fir stump bears N18°30'E 49.2'; scribed T3S R7W S1 BT.
- 47" Fir bears S68°30'E 126.5'; scribed T3S R7W S12 BT RE 2311.
- 50" Fir snag bears S15W 46.1'; scribed T3S R7W S11 BT.

Placed an Oregon State Board of Forestry metal location poster on original BT, now 60" fir stump and marked it: Sec 2 T3S R7W Sec Cor 27.2 Ft. S28E.

Dated August 15, 1952

This corner was restored by Don D. Davis, under my direction. Don D. Davis Assistant Forest Engineer



Present and witnessed by Richard A. Morris Richard A. Morris Compassman

Present and witnessed by Robert A. Young Robert A. Young Chainman