

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

Section corner common to sections 2, 3, 10, and 11, Township 1 North, Range 6 West, W.M., Tillamook County, Oregon.

ORIGINAL

Fir post, now missing, from which a:

- 22" Hemlock bears S50E 29 lks; now 22" stub 9' high, badly burnt and decayed.
- 40" Hemlock bears S58W 46 lks; now 45" stump, badly burned.
- 14" Hemlock bears N35W 62 lks; now 19" down snag, exposed scribe marks BT.
- 30" Cedar bears N37E 34 lks; now 50" stump.

RESTORED AND REWITNESSED CORNER POINT

Set 1 1/2" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY TLN R6W S3 S2 S10 S11 1952 2311," 2 1/2' in ground, from which a:

- 4" Fir bears N25°45'W 48.8'; scribed S3 BT.
- 31" Fir stub 10' high bears N17°E 41.6'; scribed TLN R6W S2 BT.
- 50" Fir stump bears S85E 58.0'; scribed TLN R6W S11 BT RE 2311.
- 42" Fir stump bears S07°30'W 31.5'; scribed TLN R6W S10 BT.

Placed an Oregon State Board of Forestry metal location poster on 42" Fir stump BT and marked it: Sec 10 TLN R6W Sec Cor 31.5 Ft. N07°30'E.

Dated November 18, 1952.

This corner was restored by Don D. Davis
Don D. Davis Assistant Forest Engineer
under my direction.



Present and witnessed by Gerald M. Schwalen, Chainman.