

Line between Sections 4/9, Township 1 North Range 9 West, Tillamook Co.

West on true line between Sections 4/9 T. 1 N R 9 W.

Station
0700

Section corner common to Sections 4, 5, 8 & 9, T. 1 N R 9 W.

12744.9

Establish E 1/16 corner Sections 5 and 8. Monumented with an iron pipe 1" x 30" and referenced as follows:

30" Hemlock S 20° E. 37.0 ft. E 1/16 S 8 B.T.

30" Hemlock N 50° W. 3.3 ft. E 1/16 S 5 B.T.

Wm. Jordan, Dave Bowden
July 6, 1960

24789.9

Restore 1/4 corner Sections 5 and 8 and monument with an iron pipe 1" x 30" and referenced as follows:

16" Fir N 7° E. 27.8 ft. 1/4 S 5 B.T.

12" Fir N 80° E 21.0 ft. 1/4 S 5 B.T.

Wm. Jordan, Dave Bowden
July 5, 1960

49779.7

Section corner 5, 6, 7 and 8, T. 1 N R 9 W. Var. 21° 30' E.

LONGVIEW FIBRE COMPANY

By Olin R. Miller, Forest Engineer.
February 27, 1961.