

FORM E-20 25M 4-45

OREGON STATE HIGHWAY COMMISSION

INTER-DEPARTMENT CORRESPONDENCE

.....Nehalem, Oregon,.....  
.....May 1st, 1946.....

SUBJECT: Reset section corner

To: Mr W.S. Coates,  
County Engineer,  
Tillamook County  
Tillamook, Oregon,

Dear Sir:

Today we are tying in to our revised location South of Tillamook, the section corner at the Northwest corner of the Hunter property and the Northeast corner of the Steiner property. This corner seems well identified both by local residents and by our work on the original location survey.

The corner is a limb which is very rotten and just about gone. So we are replacing it with a 1 1/4 inch galvanized pipe with a brass or bronze cap. Pipe is set 3 feet in the ground and sticks up 6 inches above ground. 2 x 2 white post set by pipe and to be replaced later with a 4 x 4 scribed post. Cap stamped

T 1 S R 9 W

31 | 32  
6 | 5  
T 2 S

You will perhaps want to inspect this corner when convenient to you and approve it to make it official and enter in your notes.

Yours truly,

*J. H. Spott*  
J. H. Spott

cc Mr F.D. Eason, Division Engineer

Resident Engineer

BOOK 3

BOOK 3

Page 59