

CHAINS

Page 23.

T6SR9W (cont)

I found 4x4 post in poor condition lying upon the ground with visible Mks: "S8". Found 11" hemlock, N.44°40'W., 30 Lks. with visible marks T6SR9WS6 B. Found 20" hemlock stub 10ft. high, S.46°30'E., (not S.33°E., as in original notes) 30 Lks. with visible marks T2SR9WS8BT. On the north side of the above BT is visible marks "BM8". The SW BT is a rotted stub with no marks. the NE vinemaple is gone. I set 4x4 hard: limb, mkd. S5 on NE, S6 on NW, S7 on SW, and S8 on NE sides and mark 4 new witnesses:

48" snag, N.11°W., 29½ft. Mkd. T6SR9WS6BT
 52" snag, S.80°W., 5ft. Mkd. T6SR9WS7BT
 53" snag, N.83°30'E., 30ft. Mkd. T6SR9WS5BT
 28" hemlock, S.53°E., 27ft. Mkd. T6Sr9WS8BT

Witnesses: Ed Gory
 L. Cummino
 G. Bergstrom
 by Leonard Whitmore,
 Tillamook Co. deputy surveyor
 7-22-65

T6SR10W

$\frac{1}{4} \frac{6}{7}$

$\frac{1}{4}$ Corner to sections 6-7

Original Monument: Post

Original ^{WITNESSES} Monuments:
 30" Hemlock S.37°W., 30 Lks. Mkd. $\frac{1}{4}$ SBT
 30" Hemlock N.74°E., 23 Lks. Mkd. $\frac{1}{4}$ SBT

I found the original post lying upon the ground. Found 40" Hemlock, N.74°E., 15ft. with visible scribe marks; "BT". Found 30" Hemlock stump, S.37°W., 20ft. with visible but not legible marks.

I set a squared Hemlock post and marked ²/_W new BTs:

34" Hemlock, S.17°E., 32ft. Mkd. $\frac{1}{4}$ S7BT.
 34" Hemlock, N.88°W., 30ft. Mkd. $\frac{1}{4}$ S6BT.