

# County Surveyor's Record, Tillamook County, Oregon

**CHAINS**

T3S R10W

29 | 28

32 | 33

EVALUATION AND RESTORATION OF LAND SECTION CORNERS

Section Corner common to Sections 28-29-32-33, W.M.,  
Tillamook County, Oregon

ORIGINAL: Wm. P. Wright, Surveyor, August 17, 1882

A hemlock, 10 ins. diam., for corner to sections 28-29-32-33, mkd. T3SS28 on NE, R10WS33 on SE, Section 32 on SW, S29 on NW face, with 4 notches on East and 1 on South edges, from which:

Hemlock, 8 ins. diam., bears N54°W., 17 lks. dist., mkd.

T3SR10WS29BT,

Hemlock, 8 ins., diam., bears N14°E., 5 lks. dist. mkd.

T3SR10WS28BT,

Hemlock, 6 ins. diam., bears S34°W., 16 lks. dist. mkd.

T3SR10WS32BT,

Hemlock, 7 ins., diam., bears S44°E., 20 lks. dist. mkd.

T3SR10WS33BT.

FOUND:

20" Hemlock stump, S44°E., 13.2 ft. with visible mks.

"S33" as original notes,

18" Hem. stump, N54°W., 11.2 ft. with visible mks.

"S29". The original NE and SW are gone.

RESTORED:

I set 1" pipe, and mark one new BT as follows:

36" sawed off fir stump, S54°30'W., 18½ ft. mkd.

S32CSBT. Due to the short stump I could not include all the required marks. No suitable BT for marks.

No suitable BT for Section 28.

DATED: 1-16-67

RESTORED BY: Leonard Whitmore, Till. Co. Deputy Surveyor

# County Surveyor's Record, Tillamook County, Oregon

CHAINS

★ U. S. GOVERNMENT

LAND CORNER


5680-2

1. T. 3 S. R. 10 W. No. 14-9 Cor. Sec. Mer. Will State <sup>(Rectangular)</sup> ORE N. F. SIUSLAW Dist. HeBo

2. Corner Status

3. Original Description \_\_\_\_\_ Vol. \_\_\_\_\_ Page \_\_\_\_\_ Where Recorded \_\_\_\_\_

4. Description of Corners:



GONE

5. Investigation Notes:

FOUND 20" HEM. STUMP, S. 44° E., 13<sup>2</sup> FT. WITH VISIBLE MKS. "S33"  
 AS ORIG. NOTES.  
 FOUND 18 HEM., STUMP, N. 54° W., 11<sup>2</sup> FT. WITH VISIBLE MKS. "S29"  
 THE ORIG. NE AND SW BT<sup>s</sup> ARE GONE.

7. Photo Identification

Photo No. \_\_\_\_\_  
 Ident. By: \_\_\_\_\_

8. Plane Coordinate Position Data

State \_\_\_\_\_ Zone \_\_\_\_\_  
 X \_\_\_\_\_  
 Y \_\_\_\_\_

Estab. By \_\_\_\_\_  
 Field Book No. \_\_\_\_\_  
 Where Filed \_\_\_\_\_

9. Evaluation

Authentic \_\_\_\_\_   
 Needs Verif. \_\_\_\_\_ Monument \_\_\_\_\_  
 Re-estab. \_\_\_\_\_ Survey \_\_\_\_\_  
 Land Status \_\_\_\_\_

BOOK 3

6. Signed L. Whitmore Title Forestry Tech Date 1-16-67

PERPETUATION RECORD

10. Monument: I set 1" pipe

11. Accessories I MARK ONE NEW BT:

36" SAWED OFF FIR STUMP, S, 54° 30' W., 18 1/2 FT. MKD. S32 CS BT. DUE TO THE SHORT STUMP I COULD NOT INCLUDE ALL THE REQUIRED MARKS. NO SUITABLE BT FOR SEC. 28.

Leonard Whitmore, Tilla Co. Dep. Surveyor

Field Book \_\_\_\_\_ Page \_\_\_\_\_

12. Set By \_\_\_\_\_ Title \_\_\_\_\_  
 License \_\_\_\_\_ Agency \_\_\_\_\_ Date \_\_\_\_\_

13. Recorded By \_\_\_\_\_ Volume \_\_\_\_\_ Page \_\_\_\_\_  
 (Agency) \_\_\_\_\_  
 (Date) \_\_\_\_\_ (City) \_\_\_\_\_ (County) \_\_\_\_\_ (State) \_\_\_\_\_

14. Remarks:

BOOK 3

BOOK 3 1