

County Surveyor's Record Tillamook County, Oregon

Restoration of the South $\frac{1}{4}$ corner of Section 16, T. 4 S., R. 9 W., W.M.
Found 12x10x10 Basalt stone marked: $\frac{1}{4}$ S 16 on North and $\frac{1}{4}$ S 21 on South face.
Stone being in a pile of stones on the west side of a 12" alder stump. Pile
of stones appear to be undisturbed. New road construction east of the $\frac{1}{4}$ corner.
The 12" alder stump being 2 $\frac{1}{2}$ ft. east of the corner, has a Forest Service Tag
on it labeled to that effect. A re-marked 16" Fir being south of the $\frac{1}{4}$ corner
has been dozed out of position. A 38" Fir, now a stump, bearing N. 48° E. approx-
imately 185 ft., painted and marked. Old face visible but did not cut in.
From the stone or $\frac{1}{4}$ corner we marked a 16" Fir bearing tree bearing North 41 $\frac{1}{2}$ ° East
a distance of 59.7 ft., scribed $\frac{1}{4}$ S 16 BT, Also a 16" Fir bearing South 06 $\frac{1}{2}$ ° West
86.9 ft. scribed $\frac{1}{4}$ S 21 BT.

Note: The original corner was set by Charles E. Branson, Contract #687 during
survey of 1898.

