

# County Surveyor's Record, Tillamook County, Oregon

## CHAINS

Restoration of the 1/4 corner common to Section 25 and 36, T2S, R10W, W.M.

Original corner was set in 1882, 40.25 chains East on a true line between sections 25 and 36. A post was set marked 1/4S on N face from which:

- 14" Spruce bears N 88° E, 58 lks - 1/4 S BT
- 12" Spruce bears S 10° W, 57 lks - 1/4 S BT

On May 8, 1969, I found the two Spruce BTs (now rotting stumps) with a scribed "BT" plainly evident on both.

From these original bearing trees I set a 3/4" iron pipe with 3 inch brass cap for the 1/4 corner. I marked new bearing trees as follows:

- 16" Fir bearing N 39° E 41.8 feet, scribed "BT-S25-376"
- 14" Fir bearing S 75° W 23.7 feet, scribed "BT-S36-376"

Restoration of the corner common to Sections 25, 26, 35 and 36, T2S, R10W, W.M.


Original corner was set in 1882. "Set post 4 feet long, 6 inches in diameter, 12 inches in the ground - - - etc., from which:

- 72" Fir bears N 40° W, 59 lks
- 24" Hemlock bears N 33° E, 42 lks
- 12" Hemlock bears S 3° E, 12 lks
- 10" Hemlock bears S 74° W, 35 lks"

On May 8, 1969, I found the 10" Hemlock (now a rotting stump) with a scribed S-35-BT" plainly evident. The 72" Fir (also a rotting stump) is properly located in relation to the corner but no face or marks are found.

From these original bearing trees I set a 3/4" iron pipe with 3 inch brass cap for the corner. I marked new bearing trees as follows:

- 12" Fir bearing N 54° E 26.8 feet, scribed "BT-S 25"
- 20" Fir bearing S 72° E 45.3 feet, scribed "BT-S36-376"
- 10" Fir bearing S 18° W 25.2 feet, scribed "BT-S35"
- 14" Hemlock bearing N 70° W 27.9 feet, scribed "BT-S26-376"

  
By: Charles G. Collard  
Registered Land Surveyor  
Oregon #376

Witnesses: G. W. Jaques  
B. K. Conrad

May 8, 1969