


TOWNSHIP 5 SOUTH, RANGE 10 WEST

Standard Corner, Section 35/36, T5S, R10W

See LFCo. Map #701

Found iron pipe for the standard corner, restored by Bureau of Land Management in 1962, with a brass cap marked as illustrated:



From which I found the following new bearing trees:

- 40" Fir bears S 40° E 17.0 feet 1
- 44" Fir bears N 82° E 29.30 feet 2

July 9, 1971

Found by: Russ Bass, LFCo.  
 Witnesses: Wayne Brewer, R. Thompson  
 R. McCollam, R. Mansfield

*See map A-2512*