

County Surveyor's Record, Tillamook County, Oregon

Feet

1001 Branch, 2 feet wide, course N10°E
 2358 Tony Creek, 15 feet wide, course N10°W
 2491.29 Position for the North 1/4 corner of Section 3. I set a 2 1/2" x 30" iron post with brass cap marked

T3S R9W

$$\frac{34}{3} \text{ N } 1/4$$

T4S R9W

1974 650

from which

A 22" Fir bears S55°E, 28.2 feet to face
 Scribed N 1/4 S3 BT 650.
 A 32" Fir bears S30°W, 52.6 feet to face
 Scribed N 1/4 S3 BT.

2501.12 Position for the reestablished South 1/4 to Section 34. Made a diligent search for the corner as originally established by Henry Meldrum, but could not find. I set a 2 1/2" x 30" iron post with brass cap marked

T3S R9W

$$\frac{34}{3} \text{ } 1/4$$

1974 650

from which

A 34" Fir bears N29°E, 56.3 feet to face
 Scribed S 1/4 S34 BT--Bark scribed 650.
 A 20" Fir bears N76°W, 58.6 feet
 Scribed S 1/4 S34 BT.
 A 60" Fir bears S31°E, 230 feet. This tree has an old face with scribing still visible. This could be a BT to the S 1/4 corner of Section 34 as established by County Surveyor Sappington circa 1890's. This has no bearing on the true position of this corner.

Continuing through timber on line between T3 and 4S, R9W

N89°57'34"E

4290 Spur bears N20°E
 5013.52 Position for the reestablished corner to Sections 34 and 35 as originally established by S. Caudle. A diligent search was made for both this corner and the original corner to Sections 34, 35, 2, and 3 as established by Henry Meldrum. Nothing could be found of either corner. At this point, I set a 2 1/2" x 30" iron post with brass cap marked

T3S R9W

$$\begin{array}{c} \text{CAUDLE} \\ | \\ \hline 34 \quad 35 \\ \hline 3 \end{array}$$

T4S R9W

1974 650

See map B661