


TILLAMOOK COUNTY SURVEYORS OFFICE

Section Corner common to sections 13 & 24 only, T.3N.,R.9W.,W.M.



I set a 10" concrete cylinder around found 1 1/2" iron pipe with 3" Oregon State Board of Forestry Brass Cap set in 1975, (see Tillamook County Surveyors rewitness book 5 page 368).

History of found monument

This monument was found to be as described in above said rewitness and its' accessory evidence found and/or set at that time to now be as listed below:

75" fir S.46*W. 48 links (original), now 78" stump no marks

18" fir N.25*W. 49 links (book 2 page 190), now 32" fir face is overgrown.

9" spruce S.39*W. 126 links (book 2 page 190, dated 10-31-52), now 22" spruce face is overgrown.*

18" hemlock N.36*W. 18', (book 2 page 190, dated Oct. 31 1952), and reported as N.30*W. 12.5', (book 5 page 368, dated Nov, 10 1975 and book 3 page 53 dated Oct. 6 1966), Now 34" hemlock at position reported by the later restorations.

4"X 4"X 5' white painted cedar post 1.0' SE of corner pipe(book 5 page 368); I replaced with an 84" hat section post 1.1' S.32*E.*

34" fir N.79*E. 32.7'(book 5 page 368), now 42" fir with O.D.F. yellow metal location poster attached.

In the presence of Dan McNutt & Al Dvorak

February 1989

Title Allan E Duncan, C.S.

*Tillamook County Yellow Metal location poster attached.

