

TILLAMOOK COUNTY SURVEYORS OFFICE

1/4 corner common to sections 32 T.3N.,R.9W.,W.M.
and section 5 T.2N.,R.9W.,W.M.

3N9
S 32
---+---
S 5 2N9
RS 287
1972

I Found a 3" Tillamook County Brass Cap in an 8" clay tile and cement in good condition. Very close to the ditch line of Foss County Road. See County Surveyor rewitness #65.

History of Found Monument

I found this monument to be as reported in the above said rewitness, and the accessory evidence found and/or set at that time to be as listed below.

- 4"x4"x48" O.S.B.F. post north 2.0'; Now gone.
- *96" hat section post S.20°E. 1.3'; Now S.20°E. 1.4'.
- *24" hemlock S.18°E. 56.55'; Found okay, now 43" face overgrown.
- *72" cedar stump N.70°W. 9.60' to face; Found okay scribing visible distance good between the B T.
- Stump S.18 1/2°E. 49.30'; Now a very rotten stub.

New Accessory

I set a 5/8" iron rod with red plastic cap in the west bound lane of Foss county road S.66°E. 38.14'.

I set a 5/8" iron rod with red plastic cap in the west bound lane of Foss county road S.24°23'30"W. 44.63'.

Basis of bearings was a hand compass course on the S.66°E. bearing. The interior angle was turned with a Wild T-16 transit, and the distances were measured with a DI 5 electronic distance meter. The distance between the 2 iron rods was verified with a steel tape 58.91' versus a 58.90' computed.

Location of Monument

This corner is located approximately 22' north of the road and very near the ditch line. The possibility of destruction of this corner by road maintenance crews was the reason for this referencing.

In the presence of Dan McNutt & Al Dvorak

March 1989

Title Allen E. Duncan, C.S.



BOOK 6 401