

TILLAMOOK COUNTY SURVEYORS OFFICE

Section corner common to sections 25 & 36 T.1S.,R.10W.,W.M. & sections 30 & 31 T.1S.,R.9W.,W.M.

T1S
R10W R9W
S25;S30
----+----
S36;S31
RS 287
1980

I set a 10" cast iron Tillamook County monument case around a found 1/2" iron bar with 3" Tillamook County brass cap; (see Tillamook County Surveyors rewitness card #249).

History of found Monument

I found this monument to be as reported on Tillamook County Surveyors rewitness card #249. The accessories found and/or set at that time are now as follows:

Lead plug with tack in curb N.3*E. 58.72'; (now under new curb not found).

Lead plug with tack in curb S.26*E. 105.09'; (found now S.30*E. 105.09').

Power pole # X37 S.42*W. 98.19'; (found okay, new pole # 368800).

SE corner of the Barn Tavern N.34*W. 99.63'; (found okay).

* Indicates yellow Tillamook County corner tag affixed.

Surveys and rewitnesses of reference not listed on card #249;

A-4171	Allan E. Duncan	LS 793	1980	
A-4285	Allan E. Duncan	LS 793	1980	
A-5723	Allan E. Duncan	LS 793	1988	
B-1216	Allan E. Duncan	LS 793	1986	
A-5154	George Cathey	LS 979	1984	
A-3705	John L. Carlich	LS 287	1979	
Field notebook Hayes "E"	page 23	1887		(field tie)
Field notebook AMA 13	page 52	1921		(field tie)

Monument Location

This corner is located approximately in the center of the North bound lane of Tillamook River Loop County Road Between the Barn Restaurant and lounge parking lot and Les Shwab Parking lot.

In the presence of Dan McNutt & Al Dvorak

June 1989

Title:

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Allan E. Duncan, C.S.

OREGON
JULY 14, 1907
ALLAN E. DUNCAN
793

TILLAMOOK COUNTY
SEP 19 1989
SURVEYORS OFFICE