

TILLAMOOK COUNTY SURVEYORS OFFICE

Section Corner common to Sections 35, & 34 T.2N., R.10W., W.M.
and
Sections 2, & 3 T.1N., R.10W., W.M.

T2NR10W
S34|S35
----+----
S3|S2
T1NR10W
1990

I set a 1 1/2" iron pipe with a 3" Tillamook County Surveyors Brass Cap in a 10" concrete cylinder at surface over found 1 1/2" iron pipe with 3" O.S.B.F. brass cap approximately 4.5' deep in a road fill. See Tillamook County Surveyors rewitness book 2 page 451.

History of found Monument

I found this monument to be as reported in the above said book and page, and the bearing trees found and/or set at that time to now be as follows:

None of the original bearing trees reported in said rewitness, or the "new witness" in Tillamook County Surveyors rewitness book 10 at page 122, were recovered at this time. All positions fall in the road fill area.

78" spruce N.57*W. 35.5'; (Now gone position in road fill).

26" alder S.35*E. 56.8'; (Now 22" rotten stub 8' high).

Maps of reference as follows:

B-437 1959 Richard A. Morris LS 401
A-2445 1973 John L. Carlich LS 287
A-3361 1977 John L. Carlich LS 287

New Accessory

*11" alder N.80*W. 8.19' scribed T2NR10WS34B.TCS
*9" alder N.68*E. 13.90' scribed T2NR10WS35B.TCS
*11" alder S.50*E. 14.62' scribed T1NR10WS2B.TCS
*84" steel hat section post 1.5' North.
All distances to new bearing trees measured to nail with brass washer in face between scribe marks "B" & "T".
*indicates yellow metal Tillamook County location tag attached.

Monument Location

This corner is located approximately 50' Southwest of a creek and approximately 30' Southeast of logging road # 7120.

In the presence of Dan McNutt & Al Dvorak

March 1990

Title

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Allan E. Duncan, C.S.

OREGON
JULY 14, 1907
ALLAN E. DUNCAN
793

