

TILLAMOOK COUNTY SURVEYORS OFFICE

Section Corner common to Sections 25,26,35,&36 T.2N.,R.10W.,W.M.

T2NR10W
S26|S25
---+---
S35|S36
1990

I set a 1 1/2" iron pipe with a 3" Tillamook County Surveyors Brass Cap in a 10" concrete cylinder at the found position of a 1 1/2" iron pipe, see Tillamook County Surveyors rewitness book 1 at page 328.

History of found Monument

I found this monument to be as reported in the above said book and page, and the bearing trees found and/or set at that time to now be as follows:

15" original hemlock S.45*E. 12 lks., reported in said rewitness as a 35" hemlock scribes "S36" visible on partly exposed face; (now 35" uprooted stump with visible axe marks).

23" hemlock S.14*W. 21.4'; (root hole remains).

28" hemlock N.55 1/2*E. 21.1'; (now 26" rotten stump 6' high axe marks visible).

24" hemlock N.50 1/2*W. 32.4'; (now 27" stump scribing visible on rotten face).

maps of reference as follows:

B-770	1977	Robert J. Olsen	LS 701
A-969	1961	John L. Carlich	LS 287
A-1208	1964	John L. Carlich	LS 287
B-389	1958	John L. Carlich	LS 287
B-565	1968	Harold J. Russell	LS 707

New Accessory

- *9" fir S.81*W. 5.93', scribed S35 B.T CS
- *8" hemlock N.43*W. 17.89', scribed S26 B.T CS
- *6" hemlock S.31*E. 20.43', scribed S36 B.T CS
- *8" fir N.65*E. 27.69', scribed S25 B.T CS
- *84" steel hat section post 1.5' North.

All distances to new bearing trees measured to nail with brass washer in face between scribe marks "B" & "T".

*indicates yellow metal Tillamook County location tag attached.

Monument Location

This corner is located approximately 250' North of a logging road on the West side of a small gully. I attached a Tillamook County yellow metal location poster on a 6" hemlock on the North side of the said logging road S.10*W. 225' slope distance of the corner.

In the presence of Dan McNutt & Al Dvorak

March 1990

Title

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Allan E. Duncan, C.S.

OREGON
JULY 14, 1907
ALLAN E. DUNCAN
793

