


TILLAMOOK COUNTY SURVEYORS OFFICE

1/4 Corner Common to sections 3 & 4 T.1N.,R.10W.,W.M



I set a 10" concrete cylinder around found O.S.B.F. 1 1/2" iron pipe with 3" bronze cap set in 1961, (See Tillamook County Surveyors map #B-437).

History of found monument

This is a proportion corner set by O.S.B.F.

I found this monument to be as described on the above said map and the bearing trees set at that time to now be as follows:

22" hemlock S.44 1/2*W. 61.8'; (now 36" rotten stump scribing visible on partially healed face).

12" hemlock N.36 1/2*E. 42.7'; (now 15" rotten stump scribing visible on partially healed face).

New Accessories

*12" hemlock S.11*E. 12.41' scribed 1/453B.TCS.

*10" hemlock N.30*W. 8.63' scribed 1/454B.TCS

*84" hat section post S.50*E. 1.7'.

*indicates Tillamook County Surveyors yellow metal location poster attached.


Monument location

This corner is located approximately 30' NE of a main logging road (Rockaway crossover).

In the presence of Dan McNutt and Al Dvorak

March 1990

Title



Allan Duncan, C.S.

