

TILLAMOOK COUNTY SURVEYORS OFFICE

1/4 Corner Common to Sections 5 and 6, T.4S.,R.7.W.,W.M.

T4SR7W
1/4
|
36.35
|
1962

I found a 2 1/2" iron pipe with 3" B.L.M. brass cap in a mound of stone, set in 1962. I poured an irregular mass of concrete around above monument. (See Tillamook County Surveyors rewitness book 3 at page 69).

History of found monument

I found this monument to be as described on the above said rewitness book and page and the bearing trees set and/or found at that time to now be as reported on Tillamook County Surveyors map B-1199.

Surveys and rewitnesses of reference:

B-1199 1985 Larry D Bishop L5896
Book 1 Page 513 1965 B.L.M.
Book 3 Page 69 1961 B.L.M.
Book 3 Page 94 1965 B.L.M.
Book 6 Page 176 1981 B.L.M.
(also see Tillamook County microfilm file notes of U.S.G.L.O. and B.L.M. surveys).

Monument location

This corner is located approximately 50' East of U.S.F.S. road #4-7-6, which is located approximately 0.9 miles Easterly on U.S.F.S. road #3-7-31.

In the presence of Dan McNutt and Al Dvorak

March 1990

Title

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Allan E. Duncan, C.S.

OREGON
JULY 14, 1867
ALLAN E. DUNCAN
793

3/29/90

TILLAMOOK COUNTY
MAR 30 1990
SURVEYORS OFFICE