

*INFORMATION REVIEWED BY: M.SCHWARTZ 11/96

INDEX FILE NO. C-09
RANGER DISTRICT HEBO
SIUSLAW NATIONAL FOREST
CORNER 1/4 TOWNSHIP 5S RANGE 9W
COUNTY TILLAMOOK

IS THIS CORNER ON A PROPERTY LINE (YES-NO)? NO

CORNER DIAGRAM

-|-
|
5 * 4
|
-|-

PREVIOUS RENEWALS/SURVEYS, AND,
MONUMENT(S) & ACCESSORIES FOUND OR SET (CONDITION/SOURCE):

1880, Samuel Caudle set a post, from which:
4" Vinemaple, N 76 W, 5 lks
4" Vinemaple, S 30 E, 30 lks

1893 (approx), Hayes (County Surveyor), set a post for the
corner, from which:
8" Crabapple, S 85 E, 134 lks
6" Vinemaple, S 29 W, 116 lks
(does not make mention whether or not he had original Caudle
evidence or not or to what method he set his corner)

1924, W.E. Anderson (County Surveyor) in CS# A-181
laying the deed description for K.C. Kautz, set a
pipe for this corner at 2640 feet South of the
Section Corner on the Township line (no mention of
Caudle or Hayes corners)

1968, Lester Fultz (RPE 4571) tied to Anderson's
pipe in CS# A-1605, and stated, "The former owner
of the land in which the pipe marking this possible
1/4 corner was found state this pipe was considered
by some to be a true corner. A check in the County
Courthouse showed no re-witnessing other than the
map referenced above" (he was speaking of CS# A-181).

1975, Ken Wightman (RLS 942) in CS# B-685, found nothing
of the Caudle corner, and set a Brass Cap by proportion,
from which:

A 27" Maple, N 39 E, 94.9 ft., "1/4 S4 BT"
Anderson's 2" pipe, S 64-08-45 E, 210.01 feet.
On his 7100-57 form, Wightman discussed the Hayes
corner and states, "this corner (Hayes) was found
and a pipe set in 1924 (A-181). No mention was
made as to the method in which this corner was set
and it is evident that he came south 40 chains from
the 32,33,5,4. This pipe was plowed out and another
set in its approximate position by Mr. Claus Erickson.
I found this later pipe. CS A-1605 uses this pipe
for control".

1984, Wightman and Dave Bateman (RLS 1068) in CS# 1157,



tied to the Wightman cap and returned the accessories per B-685. They set an aluminum monument for a Reference Monument marked as follows:

"T5SR9W 1/4 S4 RM 50.6 N11-11W 1984 RPLS 1068"

1988-89, Wightman in CS# B-1350 performing a corrective survey, found the position of the Anderson pipe and set an aluminum cap, from which:

An aluminum cap for a Reference Monument

N 77-10 W, 184.10 ft, marked

"1988 RM S77-10E T5SR9W 1/4 S4|S5 184.0 RPLS 942"

He obliterated the marks on the 1975 cap, removed

the RM cap, and chopped out the marks on the BT

The erroneous monument is N 64-08-45 W, 210.01 ft.

1992, M. Schwartz (USFS) found the corner as described during the Cascade Head GPS project (Tillamook C.S. B-1655).

Also found a telephone pole with a BT tag marked:

N 13 E, 126.0 ft. (pole to corner)

1996, the USFS found the corner as described as part of the Pollard Cedar Mensuration Plot GPS project.

(Tillamook C.S. #B-2027)

MONUMENT DETAIL

T5S R9W
1/4
S4 | S5
1 9 8 8
RPLS 942

LOCATION AND COMMENTS:

At approx. MP #6.1 on HWY 22 & a road west in\to Mt. Fir land, corner is at toe of fill approx. 300 feet north from the beginning of the Mt. Fir road.

PLANE COORDINATE POSITION DATA

State: OREGON (NAD 1983 (1991)) (NAD 1927)
Zone: NORTH

Geodetic Latitude: 45-09-57.70386 45-09-58.34516
Geodetic Longitude: 123-48-14.70389 123-48-10.30254
Ellipsoidal Height: 87.564 m.

State Plane Coordinates: (NORTH)

X: 2,240,336.6583

Y: 171,921.4861

UTM Coordinates: (ZONE 10)

X: 436,809.151

Y: 5,001,708.824

Established by (Agency): USFS

