



**OREGON PUBLIC LAND CORNER REPORT / RESTORATION REPORT**  
Tillamook County Surveyor's Office

<b>SECTION:</b> The CS 1/16 corner of Section 23	<b>TOWNSHIP</b> 1 South	<b>RANGE</b> 9 West
<b>COUNTY:</b> Tillamook		<b>DATE:</b> 03-18-08
<b>CORNER DESIGNATION:</b> The Center-South 1/16 corner of Section 23, Township 1 South, Range 9 West, W.M., Tillamook County, Oregon.		<b>(Please check one)</b>
		<input checked="" type="checkbox"/> Condition Report Only
		<input type="checkbox"/> Restoration
		<input type="checkbox"/> Rewitness
		<input type="checkbox"/> Unrecorded
		<input type="checkbox"/> Reset at surface
<input type="checkbox"/> Referenced Out		
<b>Previous Rewitnesses, Restorations and Surveys, etc:</b> Survey map B-734, Tillamook County Survey Records.		
<b>Found Monument(s) and Accessories (Condition &amp; Source):</b> Found a 3" diameter Oregon State Board of Forestry cap upright and in good condition. I placed a 12" diameter plastic cylinder and 120 pounds of concrete around the found monument. The cap is stamped as shown hereon. The bearing trees set on map B-734 were found at record position with both having healed faces.		
<b>Monument Set (Procedures and Description):</b> Not applicable.	<b>Sketch of Found Monument:</b>	
		
<b>New accessories set:</b> Set a 72" hat section post South 72° East 3 feet from monument.		
<b>New Bearing Trees:</b> No new bearing trees were set.		
<b>Location &amp; Comments:</b> This corner is located approximately 40' South of the centerline of Wilson River Highway on top of a steep bank.		
<b>Firm / Agency</b> Address: TILLAMOOK COUNTY SURVEYOR'S OFFICE		<b>SURVEYOR'S SEAL</b>
<b>Party Chief:</b> Joe Jensen, PLS 60067, Survey Supervisor		
<b>Notes:</b>		
<b>Witnesses:</b> Danny R. McNutt, PLS 49230, Tillamook County Surveyor; Randy Wilson, Survey Technician.		 <i>Danny R McNutt</i>

