



**OREGON PUBLIC LAND CORNER REPORT / RESTORATION REPORT**  
Tillamook County Surveyor's Office

|   |   |   |
|---|---|---|
| <b>SECTION: 18</b>  | <b>TOWNSHIP 1 South</b>   | <b>RANGE 10 West</b>  |
| <b>COUNTY: Tillamook</b>  |   | <b>DATE: 2-13-09</b>  |
| <b>CORNER DESIGNATION:</b> The West 1/4 Corner of Section 18, T. 1 S., R. 10 W., W.M. and the East 1/4 Corner of Section 13, T. 1 S., R. 11 W., W.M.  |   | <b>(Please check one)</b>   |
|   |   | <input checked="" type="checkbox"/> Condition Report Only   |
|   |   | <input type="checkbox"/> Restoration  |
|   |   | <input type="checkbox"/> Rewitness  |
|   |   | <input type="checkbox"/> Unrecorded   |
|   |   | <input type="checkbox"/> Reset at surface   |
|   |   | <input type="checkbox"/> Referenced Out   |
| <b>Previous Rewitnesses, Restorations and Surveys, etc:</b> BLM Field Notes Volume: OR-R0053 Page 64 (GLO 1S10 Pg. 4) (1857), Book 5 Page 135 (1970), Rewitness #300 (1980), Tillamook County Survey Records.   |   |   |
| <b>Found Monument(s) and Accessories (Condition &amp; Source):</b> Found a 6" X 6" Concrete Post 48" out of the ground with a "1931" on the north side and a "USA" on the south side. Found hat section post 1.5' north of monument.<br>(G.L.O.) – Did not find the 16" diameter Hemlock at (N 43° E 17 lks.).<br>(G.L.O.) – Did not find the 24" diameter Hemlock which bears (S 57° W 10 lks.).<br>(Rewitness #300) – Found Hemlock uproot (was 30") bears (East 55.4').<br>(Rewitness #300) – Found 30" diameter Hemlock (was 20") bears (S 76° W 33.55').<br>( ) Indicates record information, Tillamook County Survey Records. |   |   |
| <b>Monument Set (Procedures and Description):</b> Not applicable.   | <b>Picture of Found Monument:</b><br> |   |
| <b>New accessories set:</b> Not applicable.   |   |   |
| <b>New Bearing Trees set:</b><br>80" diameter Spruce bears N 52° 30' E 30.7', scribed, "T1S R10W 1/4 S18 BT", tagged and painted.<br>All new bearing trees have a nail and aluminum washer marked, "Till. Co. Surveyor", in face of blaze, between the scribed B and T, and a yellow metal location tag affixed.  |   |   |
| <b>Location &amp; Comments:</b> Corner is located approx. 300' south of the road to Cape Meares Lighthouse and approx. 200' northerly of a foot bridge, in a small creek.   |   |   |
| <b>Firm / Agency</b><br><b>Address:</b> TILLAMOOK COUNTY SURVEYOR'S OFFICE<br>201 Laurel Avenue<br>Tillamook, Oregon 97141  |   | <b>SURVEYOR'S SEAL</b><br><br> |
| <b>Party Chief:</b> Joe Jensen, P.L.S. 60067, Survey Supervisor   |   |   |
| <b>Notes:</b>   |   |   |
| <b>Witnesses:</b> Danny R. McNutt, P.L.S. 49230, Tillamook County Surveyor<br>Michael R. Rice, L.S.I. 16723, Survey Technician  |   |   |

