

OREGON PUBLIC LAND CORNER REPORT / RESTORATION REPORT
Tillamook County Surveyor's Office

SECTION: The SE corner of Section 30, T3N, R8W, W.M.	TOWNSHIP 3 North	RANGE 8 West
COUNTY: Tillamook		DATE: 08-28-09
The section corner common to Sections 29, 30, 31, 32, Township 3 North, Range 8 West, W.M., Tillamook County, Oregon.		(Please check one)
		<input type="checkbox"/> Condition Report Only
		<input type="checkbox"/> Restoration
		<input checked="" type="checkbox"/> Rewitness
		<input type="checkbox"/> Unrecorded
		<input type="checkbox"/> Reset at surface
		<input type="checkbox"/> Referenced Out
Previous Rewitnesses, Restorations and Surveys, etc: BLM Field Note Volume: OR-R0354 Page: 0129 1891; Rewitness Book 2, Page 227 1953; Tillamook County Survey Records.		
Found Monument(s) and Accessories (Condition & Source): Found the original GLO basalt stone with 1 notch on South face and 5 notches on East face. The original stone was found on the north edge of the found brass cap. Also found a 3" diameter Oregon State Board of Forestry Brass Cap in a mound of stone, upright, and in good condition. I placed a 12" diameter plastic cylinder and 120 pounds of concrete with a rock collar around the found monument. The monument is stamped as shown hereon.		
Found a rotten Douglas Fir stub (was a 30" Douglas Fir original bearing tree bearing N25°E 28 Links see BLM Field Note Volume: OR-R0354 Page: 0129) with partial face remaining, 6' tall on average. Searched for, but did not find the other three original GLO bearing trees.		
Found rotten stump remains of the 8' tall 48" diameter Fir stub (N44° 15'E 39.0' see Rewitness Book 2, Page 227)		
Found a 42" diameter, 15' tall rotten Fir stub no scribing visible (N53° W 5.0' a 60" Fir snag see Rewitness Book 2, Page 227)		
Found a 36" diameter, 6' tall Fir stump with unreadable rusted metal tag and no scribing visible (S84° E 59.3' a 41" Fir snag see Rewitness Book 2, Page 227)		
Found a +/- 36", 5' tall Fir stub no scribing visible (S53° W 46.6' 48" Fir stump see Rewitness Book 2, Page 227)		
Monument Set (Procedures and Description): Not applicable.		Sketch of Found Monument:
New accessories set: Set a 72" Hat Section Post with paddle board and a yellow metal location tag West a distance of 3.0'. Obtained a direct GPS occupation of the section corner. Northing = 758995.132, Easting = 7384525.750, Oregon North Zone State Plane Coordinate, U.S. Survey Feet.		
New Bearing Trees set: No new bearing trees set.		
Location & Comments: This corner is located on a very steep hillside approximately 150' South of Lost Creek Road.		
Firm / Agency Address: TILLAMOOK COUNTY SURVEYOR'S OFFICE 201 Laurel Avenue Tillamook, Oregon 97141		SURVEYOR'S SEAL
Party Chief: Joe Jensen, PLS 60067, Survey Supervisor		
Notes:		
Witnesses: Danny R. McNutt, PLS 49230, Tillamook County Surveyor. Michael R. Rice, L.S.I. 16723, Survey Technician		

G:\completed restorations\T3N8Wsec.29-30-31-32.doc

BOOK 7 524

G:\completed restorations\T3N8Wsec.29-30-31-32.doc

