



OREGON PUBLIC LAND CORNER REPORT / RESTORATION REPORT
Tillamook County Surveyor's Office

SECTION: East 1/16 corner Sections 32 and 5	TOWNSHIP: 1 South, 2 South	RANGE: 9 West
COUNTY: Tillamook		DATE: 08-29-09
The East 1/16 corner of Section 32, Township 1 South, Range 9 West, and Section 5, Township 2 South, Range 9 West, W.M., Tillamook County, Oregon.		(Please check one)
		<input type="checkbox"/> Condition Report Only
		<input type="checkbox"/> Restoration
		<input checked="" type="checkbox"/> Rewitness
		<input type="checkbox"/> Unrecorded
		<input checked="" type="checkbox"/> Brass Cap set at surface
<input checked="" type="checkbox"/> Referenced Out		
Previous Rewitnesses, Restorations and Surveys, etc: Rewitness Card #253; Survey maps A-3175, A-3226, A-4496, B-178, F-41-60, Fieldbook CL 9, Page 22, Book S3, Page 492, Tillamook County Survey Records.		
Found Monument(s) and Accessories (Condition & Source): The 3" diameter brass cap as described on Rewitness Card #253 was destroyed due to an asphalt grinding project. Found the hat section post at record position (North 17.35') and placed a new paddleboard and metal location tag on the post. () – Indicates record value from Rewitness card #253		
Monument Set (Procedures and Description): Set a 2" diameter brass cap in concrete at the road surface. The monument is stamped as shown hereon. Prior to the destruction of the 3" diameter brass cap, two reference monuments were set as points on line to the monument. A 5/8" rebar with red plastic cap stamped "TILLAMOOK CO SURVEY" located 1.5' North of an East-West fence line which bears North 14° West (compass bearing) a distance of 19.69'. A 5/8" rebar with red plastic cap stamped "TILLAMOOK CO SURVEY" located 1.5' South of an East-West fence line which bears South 14° East (compass bearing) a distance of 22.12'		Sketch of Monument Set at Surface: 
New accessories set:		
New Bearing Trees set: No new bearing trees were set.		
Location & Comments: This corner is located in the center of the asphalt pavement of McCormick Loop Road (aka Mapes County Road).		
Firm / Agency Address: TILLAMOOK COUNTY SURVEYOR'S OFFICE 201 Laurel Avenue Tillamook, Oregon 97141		SURVEYOR'S SEAL 
Party Chief: Joe Jensen, PLS 60067, Survey Supervisor		
Notes: Digital images were taken of the set surface monument.		
Witnesses: Danny R. McNutt, PLS 49230, Tillamook County Surveyor. Michael R. Rice, L.S.I. 16723, Survey Technician		

