

**OREGON PUBLIC LAND CORNER REPORT / RESTORATION REPORT**  
Tillamook County Surveyor's Office

<b>SECTION: SE COR 21</b>	<b>TOWNSHIP 2 South</b>	<b>RANGE 7 West</b>
<b>COUNTY: Tillamook</b>		<b>DATE: 11-6-09</b>
<b>CORNER DESIGNATION:</b> The Section Corner common to Sections 21, 22, 27 and 28, T. 2 S., R. 7 W., W.M.		<b>(Please check one)</b>
		<input checked="" type="checkbox"/> Condition Report Only
		<input type="checkbox"/> Restoration
		<input type="checkbox"/> Rewitness
		<input type="checkbox"/> Unrecorded
<b>Previous Rewitnesses, Restorations and Surveys, etc:</b> BLM Field Notes Volume: OR-R0345 Page 273, (GLO Book 2S7 Page 25) (1891), Tillamook County Survey Records; Rewitness Book 2, Page 123 (1952), Rewitness Book 6, Page 383 (1988), Tillamook County Survey Records.		
<p><b>Found Monument(s) and Accessories (Condition &amp; Source):</b> Found a 3" O.S.B.F. Brass Cap, leaning badly, down 0.5', under a fallen tree. The monument was set in Rewitness Book 2, Page 123 (1952). The monument is stamped as shown hereon. The original post is missing. Sawed out the fallen tree and chopped out the face of the bearing trees at N 78° E 5.0' and S 30° E 31.4' in Book 6, Page 383 to reveal the 3/4" brass washer marked "LS1998" to adjust the monument.</p> <p>(G.L.O.) – Did not find the (Hemlock 12" dia. bears S 70° E 25 lks. [16.5']).          (G.L.O.) – Did not find the (Larch 26" dia. bears S 27° W 19 lks. [12.54']).          (G.L.O.) – Did not find the (Hemlock 6" dia. bears N 29° W 49 lks. [32.34']).          (G.L.O.) – Did not find the (Hemlock 12" dia. bears N 71 3/4° E 93 lks. [61.38']).          (Book 2, Page 123) – Found rotten (60" dia. Fir Stub bears N 53° W 38.2'), 4' tall, all scribing visible.          (Book 2, Page 123) – Did not find the (30" dia. Fir Stub bears S 84° E 63.0').          (Book 2, Page 123) – Found rotten (64" dia. Fir Snag bears N 18° E 45.7'), 2' tall, no marks visible.          (Book 6, Page 383) – Found 22" dia. Fir (was 15") bears (N 14 1/2° W 21.6'), healed scar and yellow metal location tag.          (Book 6, Page 383) – Found 22" dia. Fir (was 17") bears (N 78° E 5.0'), chopped out the face, yellow metal location tag.          (Book 6, Page 383) – Found 13" dia. Fir (was 10") bears (S 30° E 31.4), chopped out the face, yellow metal location tag.          (Book 6, Page 383) – Found 23" dia. Fir (was 17") bears (S 44° W 19.0'), healed scar and yellow metal location tag.</p> <p>( ) Indicates record information, Tillamook County Survey Records.          [ ] Indicates converted value from links to feet.</p>		
<b>Monument Set (Procedures and Description):</b> Not applicable.	<b>Sketch of Found Monument:</b>	
<b>New accessories set:</b> Set 120 lbs. of concrete in a 12" dia. cylinder around monument. Set 72" hat section post with a yellow metal location tag, 3.0' North of monument.		
<b>New Bearing Trees set:</b> N/A		
<b>Location &amp; Comments:</b> Monument is located approximately 200' North of Steam Pot Road, behind an existing gravel pit.		
<b>Firm / Agency</b> Address: TILLAMOOK COUNTY SURVEYOR'S OFFICE 201 Laurel Avenue Tillamook, Oregon 97141		<b>SURVEYOR'S SEAL</b>
<b>Party Chief:</b> Joe Jensen, P.L.S. 60067, Survey Supervisor		<div style="border: 1px solid black; padding: 5px; width: fit-content; margin: 0 auto;">             REGISTERED PROFESSIONAL LAND SURVEYOR           </div>
<b>Notes:</b> Digital images were taken of the monument and the found bearing trees.		
<b>Witnesses:</b> Danny R. McNutt, P.L.S. 49230, Tillamook County Surveyor Michael R. Rice, L.S.I. 16723, Survey Technician		<div style="border: 1px solid black; padding: 5px; width: fit-content; margin: 0 auto;">             OREGON JANUARY 10, 2008 JOSEPH V. JENSEN 60067           </div>
		RENEWAL DATE: 06-30-2011

