



**OREGON PUBLIC LAND CORNER REPORT / RESTORATION REPORT**  
Tillamook County Surveyor's Office

<b>SECTION: The Northeast</b> Corner of Section 31	<b>TOWNSHIP 2 South</b>	<b>RANGE 9 West</b>
<b>COUNTY: Tillamook</b>		<b>DATE: 07-20-10</b>
<b>CORNER DESIGNATION:</b> The section corner common to Sections 30, 29, 31 and 32, Township 2 South, Range 9 West, W.M., Tillamook County, Oregon.		<b>(Please check one)</b>
		<input type="checkbox"/> Condition Report Only
		<input type="checkbox"/> Restoration
		<input checked="" type="checkbox"/> Rewitness
		<input type="checkbox"/> Unrecorded
<b>Previous Rewitnesses, Restorations and Surveys, etc.:</b> BLM Field Notes Volume: OR-R0053 Page 359; Tillamook County GLO Book 2S09, Pg. 18 (1857); Tillamook County Rewitness Card #418, Rewitness Book 6, Page 164. Rewitness Book 7 Page 254 (1997); Map A-4455, B-184, B-967, B-973, B-1137, Tillamook County Survey Records.		<input type="checkbox"/> Reset at surface
		<input type="checkbox"/> Referenced Out
<b>Found Monument(s) and Accessories (Condition &amp; Source):</b> Found a 3" diameter Brass cap, upright and in good condition, set in concrete and stamped as shown hereon. This monument was set by C. Wayne Cook, P.L.S. 1098 in 1981 in Rewitness Book 6, Page 164. Found the Hat Section post at the record position from the monument. I placed a new YMLT on post. Found the very rotten remains of an approximately 36" diameter Spruce stump with a yellow tag marked "Bearing Tree" at the base of the stump. This is an original GLO stump (was a 16" diameter Spruce tree - 1857 bearing South 44° East 43 Lks [28.38']). This stump is also described on Rewitness Card #418 as being found at GLO record position a 38" diameter stump with scribing visible.		
<b>Monument Set (Procedures and Description):</b> N/A	<b>Sketch of Found Monument::</b> 	
<b>New accessories set:</b>		
<b>New Bearing Trees Set</b> 11" diameter Douglas Fir scribed "T2SR9WS32BT" which bears South 24° East 13.70'. 12" diameter Douglas Fir scribed "T2SR9WS31BT" which bears South 25° West 54.0'. 10" diameter Douglas Fir scribed "T2SR9WS30BT" which bears North 33° West 24.97', placed a 3" x 5" yellow bearing tree tag on the side of the tree facing the road. 9" diameter Hemlock scribed "T2SR9WS29BT" which bears North 67° East 22.46'. All new bearing trees have a nail and aluminum washer marked, "Till. Co. Surveyor", in face of blaze, between the scribed B and T, and a yellow metal location tag affixed.		
<b>Location &amp; Comments:</b> This corner is located approximately 25 feet South of "JC 50 Road" of the Joe Creek road system.		
<b>Firm / Agency</b> <b>Address:</b> TILLAMOOK COUNTY SURVEYOR'S OFFICE 201 Laurel Avenue Tillamook, Oregon 97141		<b>SURVEYOR'S SEAL</b>
<b>Party Chief:</b> Joe Jensen, PLS 60067, Survey Supervisor		
<b>Notes:</b> YMLT = Yellow Metal Location Tag. [ ] = Conversion from links to U.S. Survey foot.		
<b>Witness:</b> Danny R. McNutt, PLS 49230, Tillamook County Surveyor;		

