

OREGON PUBLIC LAND CORNER REPORT / RESTORATION REPORT
Tillamook County Surveyor's Office

| | | | |
|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------|
| SECTION: South 1/16 corner of Section 13 and 14 | TOWNSHIP 3 South | RANGE 8 West | |
| COUNTY: Tillamook | | DATE: 09-21-10 | |
| CORNER DESIGNATION: The South Sixteenth Corner to Sections 13 and 14, T. 3 S., R. 8 W., W.M. | | (Please check one) | |
| | | <input checked="" type="checkbox"/> | Condition Report Only |
| | | <input type="checkbox"/> | Restoration |
| | | <input type="checkbox"/> | Rewitness |
| | | <input type="checkbox"/> | Unrecorded |
| | | <input type="checkbox"/> | Reset at surface |
| Previous Rewitnesses, Restorations and Surveys, etc: Survey map number A-2711; Rewitness Book 7, Page 261; Tillamook County Survey Records. | | | |
| Found Monument(s) and Accessories (Condition & Source): Found a 3" Oregon State Board of Forestry brass cap, as set by Map A-2711, flush in concrete and in good condition. The monument is stamped as shown hereon. Reset the rock collar and placed 120 pounds of concrete around the monument. GPS tied the monument conventionally using single-occupied GPS established control. The Oregon North Zone State Plane in NAD 83/91 coordinate for the monument is N = 613032.013, E = 7397849.210, U.S. Survey Foot, Convergence = -2° 13' 04.035745", Grid Scale = 0.99989743. Found a white painted Cedar post Northwesterly 1.2' from found monument. | | | |
| Monument Set (Procedures and Description): Not applicable. | Sketch of Found Monument: | | |
| | | | |
| New accessories set: Set a 72" hat section post North 1.7' of monument. | | | |
| New Bearing Trees set: No new bearing trees set at this time. | | | |
| Location & Comments: This corner is located approximately 20' North of Deitrick Ranch Road which is also a gravel logging road that runs in an East-West direction past this corner. | | | |
| Firm / Agency Address: TILLAMOOK COUNTY SURVEYOR'S OFFICE 201 Laurel Avenue Tillamook, Oregon 97141 | | SURVEYOR'S SEAL | |
| Party Chief: Joe Jensen, P.L.S. 60067, Survey Supervisor | | <div style="border: 1px solid black; padding: 5px; width: fit-content; margin: 0 auto;"> REGISTERED PROFESSIONAL LAND SURVEYOR </div> | |
| Notes: Digital images were taken of the found monument, the record bearing trees and new accessories. This condition report was done to perpetuate the location of the found monument, no measurements were taken to confirm its position relative to any section subdivision. | | | |
| Witnesses: Danny R. McNutt, P.L.S. 49230, Tillamook County Surveyor Michael R. Rice, L.S.I. 16723, Survey Technician | | <div style="border: 1px solid black; padding: 5px; width: fit-content; margin: 0 auto;"> OREGON JANUARY 10, 2008 JOSEPH V. JENSEN 60067 </div> | |
| | | <i>RENEWAL DATE: 06-30-2011</i> | |

