

OREGON PUBLIC LAND CORNER REPORT / RESTORATION REPORT
Tillamook County Surveyor's Office

SECTION: SE COR 23 **TOWNSHIP 2 South** **RANGE 7 West**

COUNTY: Tillamook **DATE: 6-8-10**

CORNER DESIGNATION: The Section Corner common to Sections 23, 24, 25 and 26, T. 2 S., R. 7 W., W.M.

| (Please check one) | |
|-------------------------------------|-----------------------|
| <input checked="" type="checkbox"/> | Condition Report Only |
| <input type="checkbox"/> | Restoration |
| <input type="checkbox"/> | Rewitness |
| <input type="checkbox"/> | Unrecorded |
| <input type="checkbox"/> | Reset at surface |
| <input type="checkbox"/> | Referenced Out |

Previous Rewitnesses, Restorations and Surveys, etc: BLM Field Notes Volume: OR-R0345 Pages 228 - 229, (GLO Book 2S7 Pages 3 - 4) (1891), Rewitness Book 2 Page 191 (1952), Rewitness Book 7 Page 301 (1999), Map B-2634 (2003), Map B-2916 (2005), Map B-3087 (2007), Tillamook County Survey Records.

Found Monument(s) and Accessories (Condition & Source): Found a 3" diameter O.S.B.F. Brass Cap in a mound of stone as restored in Rewitness Book 2 Page 191 (1952). The monument is stamped as shown hereon. Found an orange carsonite post S 71° E 1.3'.
 (G.L.O.) – Did not find the (20" Hemlock bears S 58° W 16 lks. [10.56']).
 (G.L.O.) – Did not find the (4" Vine Maple bears N 40° W 43 lks. [28.38']).
 (G.L.O.) – Did not find the (14" Hemlock bears N 71° E 70 lks. [46.2']).
 (G.L.O.) – Did not find the (24" Hemlock bears S 60° E 60 lks. [39.6']).
 (Book 2, Page 191) – Found rotten Fir Stub, (was 38" snag, 75' tall), 5' tall, (bears S 19 1/2° E 56.7'), no visible marks.
 (Book 2, Page 191) – Found rotten 50" Fir Stump, (was a 100' tall snag), 3' tall, (bears S 49° W 101.4'), no visible marks.
 (Book 2, Page 191) – Found 60" Fir Stump, 3' tall, (bears N 77° W 113.5'), no visible marks.
 (Book 7, Page 301) – Found 25" Fir, (was 20"), (bears N 19° E 38.5'), healed face and yellow metal location tag.
 (Book 7, Page 301) – Found 21" Fir, (was 16"), (bears S 22 1/2° W 29.7'), healed face and yellow metal location tag.
 (Book 7, Page 301) – Found 25" Fir, (was 20"), (bears S 33° E 20.9'), healed face and yellow metal location tag.
 (Book 7, Page 301) – Found 19" Fir, (was 15"), (bears N 73° W 16.2'), healed face and yellow metal location tag.
 [] Indicates converted value from links to feet.
 () Indicates record information, Tillamook County Survey Records.

| | |
|---|----------------------------------|
| Monument Found (Procedures and Description): N/A | Sketch of Found Monument: |
|---|----------------------------------|

New accessories set: Set 120 lbs. of concrete in a 12" dia. cylinder around the monument. Reset Rock collar and set a 72" hat section post with a yellow metal location tag North 2.0' from the monument.

New Bearing Trees set: N/A

| | |
|--|---|
| Location & Comments: | SURVEYOR'S SEAL |
| Firm / Agency Address: TILLAMOOK COUNTY SURVEYOR'S OFFICE 201 Laurel Avenue Tillamook, Oregon 97141 | <div style="border: 2px solid black; padding: 5px; margin-bottom: 5px;"> REGISTERED PROFESSIONAL LAND SURVEYOR </div> <div style="border: 2px solid black; padding: 5px; margin-bottom: 5px;"> OREGON JANUARY 10, 2008 JOSEPH V. JENSEN 60067 </div> <p><small>RENEWAL DATE: 03-30-2011</small></p> |
| Party Chief: Joe Jensen, P.L.S. 60067, Survey Supervisor | |
| Notes: Digital images were taken of the monument and accessories. | |
| Witnesses: Danny R. McNutt, P.L.S. 49230, Tillamook County Surveyor Michael R. Rice, L.S.I. 16723, Survey Technician | |

