

**OREGON PUBLIC LAND CORNER REPORT / RESTORATION REPORT**  
**Tillamook County Surveyor's Office**

<b>SECTION:</b> The Southeast Corner of Section 4	<b>TOWNSHIP</b> 2 South	<b>RANGE</b> 9 West
<b>COUNTY:</b> Tillamook		<b>DATE:</b> 08-04-11
<b>CORNER DESIGNATION:</b> The Section corner common to Sections 3, 4, 9, 10, Township 2 South, Range 9 West, W.M., Tillamook County, Oregon.		<b>(Please check one)</b>
		<input checked="" type="checkbox"/> Condition Report Only
		<input type="checkbox"/> Restoration
		<input type="checkbox"/> Rewitness
		<input type="checkbox"/> Unrecorded
		<input type="checkbox"/> Reset at surface
<b>Previous Rewitnesses, Restorations and Surveys, etc.:</b> BLM Field Notes Volume: OR-R0053 Page 345; Tillamook County GLO Book 2S09, Pages 10-11 (1857); Tillamook County Rewitness Card #357; Tillamook County Rewitness Book 1, Page 1; Tillamook County Rewitness Book 5, Page 119; Tillamook County Rewitness Book 6, Page 158; Hayes Fieldbook 'F' Page 96; Survey Map B-301, B-509, B-615, B-2506, B-3250, A-1681, A-3738, A-5141, A-3306, P-700, F-17-5, Tillamook County Survey Records.		
<b>Found Monument(s) and Accessories (Condition &amp; Source):</b> Found a 3" diameter Tillamook County Surveyor Brass cap, up 1.0' from ground surface. Found monument is upright and in good condition and is inside a 10" tile with concrete in a swamp. The cap is stamped as shown hereon. Found a 30" diameter Alder tree with a 'Do not cut' tag attached at record position (was an 18" Alder tree bark scribed 'S3BTCS' bearing N.23°E 47.1'). Found an uprooted Spruce tree with tags attached (was a 24" Spruce tree scribed "S10BTCS" bearing S.21°45'E 20.3'). Found a 6" x 6" Air Base fence post leaning North (was a 6" x 6" Air Base fence post with cup tack in scribed circle 30" above ground bearing N.52°30'W 12.9'). Found an Alder tree approximately 12" in diameter with stretched scribing visible leaning severely to the North with a 'Do not cut' tag attached (was a 7" diameter Alder tree bark scribed "S9BTCS" bearing S.51°W 16.15'). Found a rotten 4" x 4" post with scribing visible (was a 4" x 4" x 48" post at 0.90' East).		
<b>Reference monument location:</b>	<b>Sketch of Found Monument::</b>	
<b>New accessories set:</b> We set GPS established control to conventionally tie the corner monument. The two (2) control monuments (5/8" rebar with yellow plastic cap stamped "Tillamook Co. Random") are included as references to the found corner monument. The Oregon North Zone State Plane in NAD 83/91 grid coordinate position for the corner monument is N = 656120.692, E = 7359403.175, U.S. Feet. The Oregon North Zone State Plane in NAD 83/91 grid coordinate position for monument number 1 is N = 656028.430, E = 7359282.756, U.S. Feet. The Oregon North Zone State Plane in NAD 83/91 grid coordinate position for monument 2 is N = 655776.141, E = 7359389.597, U.S. Feet. This corner has been conventionally field tied twice with the results being averaged.		
<b>New Bearing Trees Set:</b> No new bearing trees set.		
<b>Location &amp; Comments:</b> This corner is located approximately 80 feet West of a sharp curve in Brickyard County Road in a swampy area about 10' East of a North-South running fence at the Port of Tillamook Bay property.		
<b>Firm / Agency</b> <b>Address:</b> TILLAMOOK COUNTY SURVEYOR'S OFFICE 201 Laurel Avenue Tillamook, Oregon 97141		<b>SURVEYOR'S SEAL</b>
<b>Party Chief:</b> Joe Jensen, PLS 60067, Survey Supervisor, Deputy County Surveyor.		
<b>Notes:</b> Digital images were taken of the monument and the accessories.		
<b>Witness:</b> Danny R. McNutt, PLS 49230, Tillamook County Surveyor; Michael R. Rice, L.S.I. 16723, Survey Technician		