

**OREGON PUBLIC LAND CORNER REPORT / RESTORATION REPORT**  
**Tillamook County Surveyor's Office**

<b>SECTION:</b> Southeast corner of Section 16	<b>TOWNSHIP</b> 4 South	<b>RANGE</b> 7 West
<b>COUNTY:</b> Tillamook		<b>DATE:</b> 01-22-12
<b>CORNER DESIGNATION:</b> The Section corner common to Sections 15, 16, 21 and 22, Township 4 South, Range 7 West, W. M.		<b>(Please check one)</b>
		<input checked="" type="checkbox"/> Condition Report Only
		<input type="checkbox"/> Restoration
		<input type="checkbox"/> Rewitness
		<input type="checkbox"/> Unrecorded
		<input type="checkbox"/> Brass Cap set at surface
<input type="checkbox"/> Referenced Out		
<b>Previous Rewitnesses, Restorations and Surveys, etc:</b> BLM Field Note Volume: OR-R0118 Page: 0788; BLM Field Note Volume: OR-R0584 Page: 0229; Rewitness Book 1, Page 513; Rewitness Book 3, Page 79; Rewitness Book 6, Page 176a and 176b; Map B-590, B-501, B-1559, Tillamook County Survey Records.		
<b>Found Monument(s) and Accessories (Condition &amp; Source):</b> Found a 3" diameter BLM Brass Cap upright and in condition and flush with the ground. The found monument is stamped as shown hereon. Found a 17" x 7' tall rotten fir stump with a healed face (was a 12" diameter Douglas Fir tree bearing North 82° East, 9-1/2 lks. dist., mkd. 363 T4S R7W S15 BT see Rewitness Book 3, Page 79); Found a 28" x 10' tall fir stump with a healed face (was a 17" diameter Douglas Fir tree bearing South 30-1/2° East, 82 lks. dist., mkd. 363 T4S R7W S22 BT see Rewitness Book 3, Page 79); ); Found a 31" x 5' tall fir stump with a healed face (was a 24" diameter Douglas Fir tree bearing South 44-1/2° West, 23 lks. dist., mkd. 363 T4S R7W S21 BT see Rewitness Book 3, Page 79); ); Found a 28" diameter fir tree with no visible marks (was a 10" diameter Douglas Fir tree bearing North 46-1/2° West, 14-1/2 lks. dist., mkd. 363 T4S R7W S22 BT see Rewitness Book 3, Page 79).		
<b>Monument Set (Procedures and Description):</b> N/A	<b>Sketch of Found Monument:</b>	
<b>New accessories set:</b> No new accessories set.		
<b>New Bearing Trees set:</b> No new bearing trees were set.		
<b>Location &amp; Comments:</b> This corner is located at Bible Creek Ranch behind a locked gate.		
<b>Firm / Agency:</b> Address: TILLAMOOK COUNTY SURVEYOR'S OFFICE 201 Laurel Avenue Tillamook, Oregon 97141		<b>SURVEYOR'S SEAL</b>  
<b>Party Chief:</b> Joe Jensen, PLS 60067, Deputy County Surveyor and Survey Supervisor;		
<b>Notes:</b>		
<b>Witnesses:</b> Danny R. McNutt, PLS 49230, Tillamook County Surveyor.		



BOOK 8 003