

OREGON PUBLIC LAND CORNER REPORT / RESTORATION REPORT
Tillamook County Surveyor's Office

SECTION: Southeast corner Section 17	TOWNSHIP: 3 South	RANGE: 7 West
COUNTY: Tillamook		DATE: 08-17-12
The Section corner common to Sections 16, 17, 20 and 21, Township 3 South, Range 7 West; W.M., Tillamook County, Oregon.		(Please check one)
		<input checked="" type="checkbox"/> Condition Report Only
		<input type="checkbox"/> Restoration
		<input type="checkbox"/> Rewitness
		<input type="checkbox"/> Unrecorded
		<input type="checkbox"/> Brass Cap set at surface
<input type="checkbox"/> Referenced Out		
Previous Rewitnesses, Restorations and Surveys, etc: See BLM Field Note Volume OR R0636 Page 073		
Found Monument(s) and Accessories (Condition & Source): Found an iron fence post with a metal location tag East 0.4'. Original GLO bearing trees: A decayed fir stump, size indeterminate, bears N. 64 1/2° E., 104 lks. dist., no marks visible. Now- Found same at record location. A decayed fir stump, size indeterminate, bears S. 10 1/2° E., 84 lks. dist., no marks visible. Now- Found same at record location. A decayed fir stump, size indeterminate, bears S. 11 1/2° W., 87 lks. dist., no marks visible. Now- Found same at record location. A decayed fir stump, size indeterminate, bears N. 82 1/2° W., 24 lks. dist., no marks visible. Now- Found same at record location. 1959 BLM bearing trees: A Fir, 19 ins. diam., bears N. 75° E., 16 lks. dist., mkd. T3SR7WS16BT. Now- Found a 24" dia. fir with healed face and tagged with a BLM metal location tag. A Fir, 12 ins. diam., bears S. 41 1/2° E., 41 lks. dist., mkd. T3SR7WS21BT. Now- Found an 18" dia. fir with healed face and tagged with a BLM metal location tag. A Fir, 15 ins. diam., bears S. 45 1/4° W., 36 1/2 lks. dist., mkd. T3SR7WS20BT. Now- Found a 24" dia. fir with healed face and tagged with a BLM metal location tag. A Fir, 20 ins. diam., bears N. 27 1/2° W., 18 lks. dist., mkd. T3SR7WS17BT. Now- Found a 26" dia. fir with healed face and tagged with a BLM metal location tag.		
Found Monument Description: Found a 3" diameter U.S. Department of the Interior Bureau of Land Management brass cap upright and in good condition and stamped as shown hereon.	Sketch of Found Monument: <div style="text-align: center;"> </div>	
New accessories set: No new corner accessories were set.		
New Bearing Trees set: No new bearing trees were set.		
Location & Comments: This corner is located approximately 2500' down a blocked and overgrown logging road and approximately 50' North of the existing road.		
Firm / Agency Address: TILLAMOOK COUNTY SURVEYOR'S OFFICE 201 Laurel Avenue Tillamook, Oregon 97141		SURVEYOR'S SEAL <div style="border: 1px solid black; padding: 5px; display: inline-block;"> REGISTERED PROFESSIONAL LAND SURVEYOR </div> <i>Joseph V. Jensen</i> <div style="border: 1px solid black; padding: 5px; display: inline-block;"> OREGON JANUARY 10, 2006 JOSEPH V. JENSEN 60067 </div> RENEWAL DATE: 08-30-13
Party Chief: Joe Jensen, PLS 60067, Survey Supervisor		
Notes:		
Witnesses: Danny R. McNutt, PLS 49230, Tillamook County Surveyor		

