

TILLAMOOK COUNTY REWITNESS

#78

SEC. $\frac{1}{4}$ COR. 9/10 T 2 N R 10 W., WM.


HISTORICAL: A Proportioned Point Established and set by John Carllich in 1958. see Map B-380.

CONDITION	FOUND:	NO GLO RTs FOUND
Ed good (B-380)	28" Hem. stamp with face and scribe marks "287" visible, bears N 28° 15' E 5.03 ft.	
Ed (B-380)	34" Hem. stamp, Nothing visible, bears S 43° 30' W 10.28 ft.	
Ed rotted (B-380)	Rotted spruce limb with pointed end at the position established by Carllich.	

COMMENTS:

REWITNESS

1 SET A $1\frac{1}{2}$ " x 30" IRON PIPE WITH A BRASS CAP SET IN CONCRETE.



* 72" Hat Section 15 East
NEW ACCESSORY: None available

COMMENTS: 1 Set a C.S.B.C. in place of the spruce limb. Area has been logged off and burnt. The corner lies approx. 100' East of the crown road # 9500, approx. 300' south of intersection of # 9500 to 9510.

IN THE PRESENCE OF: TERRY JONES
GALE ARTHUR

DATE: 6/15/81

PHOTO#: 280

* = County corner tag affixed.

TITLE