

1413  
2324

TILLAMOOK COUNTY REWITNESS # 81

N.W. 24 COR. 1413  
2324 T 2 N R 10 W., WM.  
S. E. 14

HISTORICAL: GLO 2N10<sup>P. 21</sup> ± 1873 SET POST

BOOK	PAGE	MAPS
2	189	A-2183
		B-380
		B-844
		B-565

CONDITION DISTURBED FOUND: 3/4" PIPE LAYING HORIZONTAL

FRAME MARKS. VISIBLE	SEE	12" FIR	N. 59° E. 5 LKS.	GLO Pg. 21
FD. STUMP SCRIBING VISIBLE		6" FIR	S. 80° E. 17 LKS.	GLO Pg. 21
NOT FD		9" FIR	S. 25° W. 24 LKS	GLO Pg. 21
FD. NOW STUMP 4" HIGH		36" FIR	N. 2° E. 20 ± FT	BK. 2 Pg. 189
FD. NOW STUMP 6" HIGH		28" FIR	S. 30° E. 17 ± FT	BK. 2 Pg. 189

COMMENTS: FD. POSITION OF 12" GLO FIR TO BE N 59° W INSTEAD OF N 59° E. AS REPORTED IN BK. 2 Pg. 189. ROLLED REMAINS DOWN THE HILL AWAY FROM CORNER POSITION

REWITNESS

1 SET 1 1/2" IRON PIPE WITH 3" BRASS CAP IN 10" TILE & CONCRETE FROM FD. BTS.

T 2 N R 10 W  
S 14 | S 13  
S 23 | S 24  
RS 287  
1980

\* 86" Hat Section NORTH 15 FEET

NEW ACCESSORY:

* 30" FIR STUMP	S. 40° W. 2660'	S 23 BT CS

COMMENTS: THIS CORNER IS LOCATED ± 100' EAST OF A LANDING & ± 150' WEST OF THE BOTTOM OF A DRAW IN A CLEAR CUT AREA. FD. 3/4" IRON PIPE LAYING HORIZONTAL, ITS POSITION WAS DESTROYED BY LOGGING! IN THE PRESENCE OF: DAN McNUTT GALE ARTHUR

DATE: 6-80

COB\*  
PHOTO#: 280\*

\* County corner tag affixed.

TILLAMOOK COUNTY REWITNESS TITLE