

TILLAMOOK COUNTY REWITNESS # 135  
 1/4 COR. SEC. 22  
 27 T 3N R 10 W., WM.

HISTORICAL: GLO Pg. 27 3N10 1873


BK.	Pg.	MAPS
CTS	17	B-1088
		B-735 DIFFERENT CORNER

CONDITION GONE	FOUND, NOTHING AT CORNER POINT
FD. ROOT CROWN @ POSITION	28" HEMLOCK N. 89 W. 40 LKS GLO Pg 27
GONE POSITION FALLS BESIDE FIR UPROOT	9" HEMLOCK S. 48 E. 34 LKS GLO Pg 27
FD. LINE BLAZE ON	80" FIR STUMP ± 1 CHAIN EAST
AT POSITION FOR SE. B.T. FD. 50' FIR UPROOT FACE ROTTED AWAY	
OVERGROWN BLAZE ± 6' ABOVE ROOT CROWN	

COMMENTS:

REWITNESS

1 SET 1 1/2" IRON PIPE IN 10" CONCRETE CYLINDER WITH 3" BRASS CAP  
 60" Hat Section 15 FEET N, S, E, W ?



NEW ACCESSORY: DISTANCES TO NAIL WITH WASHER IN FACE

* 12" D. FIR <sup>NOW STUMP</sup> 6-5-82	N. 23° 06' W. 23' ±	1/4 S 22 B.T. CS
* 22" D. FIR <sup>NOW STUMP</sup> 6-5-82	S. 62° 30' W. 35' ±	1/4 S 27 B.T. CS

COMMENTS: THIS CORNER IS LOCATED ON THE SE SLOPE OF A RIDGE IN TIMBER ± 75' WEST OF A CLEAR CUT. CORNER IS NOW ± 6' OF POWERLINES ± 10' EAST OF 3 POLE STRUCTURE.

IN THE PRESENCE OF: AL DUNCAN RS 793  
 GALE ARTHUR  
 DAN MCNUTT

DATE: 3-4-83 PHOTO#: \_\_\_\_\_

\* = County corner tag affixed.

TITLE