

127

TILLAMOOK COUNTY REWITNESS

187

W. SEC.
1/4 COR. E.

12/7 T 1 S R 10/9 W., WM.

HISTORICAL:


MAP A-271		
Book 5 Pg 208		
GLO Book T1S R10W Page 7		
MAP A-49		

CONDITION Good	FOUND: ± 1/4" Iron Pipe ± 6" below Surface		
Gone	4'x4'x48" Post	West 24°	BK 5 Pg 208
Fd @ bearing & dist.	* 14" Cedar	West 35° 08'	BK 5 Pg 208
Fd @ bearing & distance	Power pole	S 41° E 39° 28'	BK 5 Pg 208

COMMENTS: Both GLO Bearing Trees are gone!

REWITNESS

1 SET 1/4" Iron Bar with 3" Brass in Concrete Level with Pavement feet



* 96 Hat Section
* RESET HAT SECTION IN FENCE CORNER N. 51° W. 33 ± 01 ± 12-88
NEW ACCESSORY:

COMMENTS: Corner is located ± 1 EAST of Centerline Stripe.

IN THE PRESENCE OF: Geo. W. Urrey A.E.D. RS 793

Gale Arthur

Roger Knipple

John Louis Carlich C.S. RS 287

DATE: 5-72

PHOTO:

* = County corner tag affixed.

TILLAMOOK COUNTY REWITNESS

TITLE