

TILLAMOOK COUNTY REWITNESS

#202

SEC. 17 COR. 20 T 15 R 9 W., WM.

GLO-1857 - Page 68

HISTORICAL: Bk 53 Page 194 1898

MAP F-12-14

MAP F-16-3 W.S. COATES

MAP B-535 H.J. Russell 1967

BK 1 Page 80 1949 E. 3

BK 4 Page 55 1949 E. 3


CONDITION	FOUND:		
	1 1/2" Iron Pipe with tack		
GOOD Scribing Visible*	36" Alder	S 65° E 110 ^s	S 68° E 110 ST field
Rotting / now Stamp	36" Alder	S 79° W 153 ^s	

COMMENTS: Placed 2" Iron Pipe over found 1 1/2" Iron Pipe.

REWITNESS

1 SET 2" Iron Pipe with 3" Brass Cap with Cement & Tile

OCT 1971



*96 " Hat Section S.E. NORTH 25-feet

NEW ACCESSORY:

*60" SCHOOL MARM SPRUCE No°	11166

COMMENTS: Set Hat Section in Right of Way fence. Placed Yellow bearing tag and "Do Not Cut" tag on found b.t. bearing S 65° E 110^s. batimer road apparent & is ± 60 feet north. Wilson river is ± 200 feet south.

IN THE PRESENCE OF: Gale Arthur
George Urey

DATE: 12-3-69

PHOTO#:

TITLE
GWA

* = County corner tag affixed.