

TILLAMOOK COUNTY REWITNESS

#203

SEC. 5

WEST $\frac{1}{16}$ COR.

$\frac{17}{20}$ T 1 S R 9 W., WM.

HISTORICAL: MAP B-506 W.E. Anderson

MAP B-535 H.J. Russell 1967

MAP A-1310 W.A. MARHAM

MAP A-1535 J.L. CARLICH

CONDITION

FOUND:


	1 1/2" Iron Pipe prior to the construction of the Latimer Road. W.E. Anderson, County Surveyor set the 1 1/2" Iron Pipe by single proportion and tied the corner to his center line Traverse.
	I witnessed the above pipe before construction and reset the corner after completion of construction.

COMMENTS:

REWITNESS

NOW REPLACED (2-4-72) WITH BRASS CAP AS SHOWN IN SKETCH (WITH CONCRETE)
 I SET 2 1/2" Iron Pipe 3" above ground level

* 4" x 4" x 48" Post N. NORTH 1° feet



NEW ACCESSORY: ALL DISTANCES TO SCRIBED FACE

18" ALDER	N 18° E	5544
21" ALDER	N 60° W	70 1/2

COMMENTS: Corner is located on the northerly side slope of Latimer Road. ± 70 FT WEST

NO "DO NOT CUT" TAGS

IN THE PRESENCE OF:

AL DUNCAN 793

Roger Knipple Gale Arthur
 Feb. 1972

GALE ARTHUR

DATE: 12-12-66

PHOTO#:

* County corner tag affixed.

TITLE