

18
19

TILLAMOOK COUNTY REWITNESS

#208

N. ~~19~~ SEC. 18
 1/4 COR. 19 T 15 R 9 W., WM.
 S. ~~E~~ 18

BOOK 10 Page 7 1887
 HISTORICAL GLO 159 Page 68
 Book 4 Page 61 WE Anderson 1949
 Book 3 Page 229 1965
 Book 1 Page 83 1949
 MAP A-683 MAP A-800
 MAP B-552 1948 MAP B-535 1967


CONDITION	FOUND:
Fair / rusting	2" Iron Pipe flush with ground
	60" STUMP N36°25'W 228°
	NO OTHER BEARING TREES FOUND

NO VISIBLE SCRIBING
 STUMP WAS ROTTEN

COMMENTS: Previously I set a 4x4 cedar post 48" long which is now gone.

REWITNESS

I SET 2" Iron Pipe with Brass Cap Marked as sketched in 6" tile with cement
 * 84 " Hat Section * Post N ~~NE~~ NORTH 15 feet



NEW ACCESSORY:

70 foot Power Pole	N 15° 30' W	263.05
10" Spruce	S 43° W	182.30
10" TILE FILLED WITH CEMENT		

COMMENTS: Power Pole is scribed as follows; 1/4 S 18 BT CS
 10" Spruce is scribed as follows 1/4 S 19 BT CS

Corner is located EAST of Southern Pacific Railroad in a pasture.

IN THE PRESENCE OF: Gale Arthur

DATE: 7-1-69

PHOTO#:

* = County corner tag affixed.

TITLE: G.W.