

21 22  
28 27

TILLAMOOK COUNTY REWITNESS #213

SEC. 21 | 22  
Section COR. 28 | 27 T 1 S R 9 W., WM.

Hays Book "F" Pg 1

HISTORICAL: GLO Pg 56-57 BK Pg

MAPS	MAPS	6	408
A-377	A-1882	1	89
A-700 Subdivision	A-1884	5	120
A-1400	A-821	53	113
A-1615		4	65
A-1812	Refer to field notes by JLC & AED		
FOUND:	Both subdivided sec 22 159		

CONDITION	FOUND:
PLUGGED & TACKED	2" IRON PIPE ± 8" Below Surface BK 5 Pg 120
NOW 28" FIR	Fir 24" WEST 208 BK 1 Pg 84 = BK 4 Pg 65
NOW 36" FIR	Fir 30" S 35W 38° BK 1 Pg 84 = BK 4 Pg 65
NOT VISIBLE	USBM Brass Disk N 42E 13' BK 5 Pg 120 = BK 4 Pg 65

COMMENTS: GLO SET A POST-- AT THAT TIME NO B.T.S WERE AVAILABLE-- TRENCH WERE MADE

REWITNESS

1 SET 2" IRON PIPE WITH BRASS CAP IN TILE AND CONCRETE FLUSH WITH PAVEMENT

"x" "x" "Post N.W. S. E. Hat Section feet

T 1 S R 9 W  
21 | 22  
28 | 27  
RS 287  
1973

NEW ACCESSORY:


COMMENTS: Between New HWY # 6 AND OLD Wilson RIVER HWY -- ± 100 FEET SOUTH OF NEW HWY # 6 -- IN EAST LANE OF ROAD RUNNING N-S BETWEEN OLD & NEW HWY IS THE SECTION CORNER.

IN THE PRESENCE OF: Gale Arthur  
D. McNitt  
G.W.U.

DATE: 12-19-73

PHOTO#:

\* - County corner tag affixed.

TITLE