

TILLAMOOK COUNTY REWITNESS #214  
 SEC. 22 T 15 R 9 W., WM.  
 EAST 1/4 COR.

HISTORICAL: GLO -- Page 54 & 20 & 11  
 MAP A-103 W.S. COATES - 1918  
 MAP A-700 J.L. Carlich 1957 Refer to field Notes Sec 22 159  
 BK 3 Page 136 Lynn M. Roseberry GLO 1958  
 MAP A-964 J.L. Carlich  
 MAP F-21-19 1942 MAP F-12-24 1948 MAP F-28-3 1941


Field Notes by WE Anderson  
 for Ted Jacobs 1946

CONDITION Good	FOUND: 2" Iron Pipe		
Good	BT 8" CEDER	NOW 16"	S 82° E 27 <sup>70</sup>
	BT 6" CEDER	NOW 14"	S 25° E 53 <sup>80</sup>

COMMENTS:

REWITNESS

1 SET 2" Iron Pipe with 3" Brass Cap in Concrete & Tile  
 "x" "x" " Post N.W. feet  
 96 " Hat Section S. E SOUTH 1<sup>15</sup> feet



NEW ACCESSORY:  
 PUT "DO NOT CUT" TAGS ON BTS  
 PUT YELLOW CORNER TAGS ON BTS

COMMENTS: Corner is located in a group of Holly trees  
 Corner is ± 90 feet northerly of north bank of Wilson River and  
 ± 60 feet southerly of SOLLIE SMITH ROAD. Corner is near a group  
 of CEDER TREES which are in a line going North & South.

IN THE PRESENCE OF: Gale Arthur  
 George Arrey

DATE: 1969

PHOTO#:

TITLE  
 G.W.U.

\* = County corner tag affixed.