



TILLAMOOK COUNTY REWITNESS #269
 COR. 2 T 15 R 10 W., WM.

S.S.W. DLC.# 38 George Webber T1SR10W
 42 George Webber T1NR10W

HISTORICAL:

MAP	MAP	Book	Page
A-300	A-936	4	73
A-256	A-1282	1	87
A-279	A-1725	5	103
A-331	F-40-57	HAYS "F"	69
A-487	C-278	Refer to field notes for ED Remington Survey (Sec 2)	

CONDITION

FOUND	FOUND	FOUND	FOUND	FOUND
14" Pine N25°00'W	85 ³⁵	1950	BK 4	Pg 73
14" Fir N82°16'W	36 ²⁵	1950	BK 4	Pg 73
Power Pole #1568 (E3)	N61°E 32 ⁵⁷	1965	BK 5	Pg 103
N.W. Cor. Hse. Conc.	S59°E 95 ⁷⁶	1965	BK 5	Pg 103
4"x4"x48" POST	N85°W 26 ²⁵	1968	BK 5	Pg 103

Refer to R. E. HEYDEN SURVEY NOTES (Sec 2)
 COMMENTS: Refer to C. DARR SURVEY NOTES (Sec. 2) MAP A-1282

REWITNESS

I SET 2" IRON PIPE WITH 3" BRASS CAP
 WITH 10" TILE AND CEMENT IN PLACE OF STONE.
 4" x 4" x 48" Post N85°W 26²⁵ feet
 96" Hat Section IN PLACE OF POST 25⁸ FEET
 D.P. 12-88

S.S.W.
 GEO WEBBER
 DLC L
 RS 287
 1974

NEW ACCESSORY:

COMMENTS: Corner is located AT intersection
 OF Bewley Avenue - Doughty Road

STONE WAS DESTROYED TO MAKE ROOM FOR 2" IRON PIPE + 3" BRASS CAP

IN THE PRESENCE OF: GALE ARTHUR
 DAN McNUTT

DATE: APRIL 1974 PHOTO#: _____ TITLE _____

* = County corner tag affixed.