

TILLAMOOK COUNTY REWITNESS #270

W. 1/4 COR E. SFC. 21 T 15 R 10 W., WM.

HISTORICAL: GLO-Page 24-1857

MAPS

	BK 4 Pg 73	A-256	
GLO-Pg 24 =>	HAYS BK "F" Pg 88	A-300	1947
	BK 5 Pg 96	A-2091	1971
	BK 1 Pg 87	A-1518	1967
	BK 1 Pg 2		

(BK 1 Pg 2) = (GLO Pg 24) (BK 1 Pg 87) = (BK 4 Pg 73)

CONDITION

FOUND: 2" Iron Pipe @ corner position


GONE	Hemlock 40"	S80°E 22 ^{1/2} 14 ^{5/2}	GLO Pg 24	1857
Spruce ±70" Stump @ dist.	Spruce 56"	S75°W 22 ^{1/2} 14 ^{5/2}	BK 1 Pg 2	1857
36" Hemlock Stump Fd Scribing	Hemlock 22"	S07 1/2°E 2 1/4	BK 1 Pg 87	1950
27" Hemlock Stump Fd Scribing	Hemlock 16"	N77°E 2 1/2	BK 1 Pg 87	1950
Spruce Stump Fd Scribing	Spruce Stump 15" x 12" DBH	N19°E 33 00	BK 5 Pg 96	1970
Spruce Stump Fd Scribing	Spruce Stump 8" x 50"	N42°W 43 43	BK 5 Pg 96	1970

Fd bearing to be N52°W rather than N42°W

COMMENTS:

REWITNESS

1 SET 2" Iron Pipe with Brass Cap in Conc and tile



*96 " Hat Section S. South 06

NEW ACCESSORY:

8" Hemlock S58°W 14 40

COMMENTS: Corner is located ±600 feet in back of Remington Resident's & ±100 feet into Brush-swamp-wooded-area. Replaced found Iron Pipe with Brass Cap as stated above.

IN THE PRESENCE OF:

George W Urrey
Gale Arthur
Roger Knipple

DATE: 4-72

PHOTO#:

* = County corner tag affixed.