

28 | 27  
33 | 34

TILLAMOOK COUNTY REWITNESS #325

SEC. 28 | 27  
SECTION COR. 33 | 34 T 1 S R 10 W., WM.


HISTORICAL: FOR DETAILED REPORT SEE  
REPORT DATED 3-30-88 IN C.S. RE-  
WITNESS BOOK 6 @ PAGE 399. BY GREGORY  
A. CRITES L.S.#1887.

CONDITION GOOD FOUND 3/4" IP WITH 2 1/2" BRASS CAP


COMMENTS:

REWITNESS

1 SET IRREGULAR MASS OF CONCRETE AROUND FOUND 3/4" IRON PIPE  
WITH 2 1/2" BRASS CAP SET BY UNKNOWN PARTY  
\* 72" Hat Section NORTH 13 FEET



NEW ACCESSORY: 2/9/09-New Bearing Tree Tags on Existing BT's

* 6" SPRUCE	S. 3° W. 8 <sup>03</sup>	S 33 B.T CS
* 6" FIR	S. 56° E. 11 <sup>50</sup>	S 34 B.T CS
* 7" FIR	N. 15° E. 10 <sup>18</sup>	S 27 B.T CS
* 7" FIR	N. 73° W. 10 <sup>56</sup>	S 28 B.T CS

DISTANCES MEASURED TO NAIL WITH BRASS WASHER IN FACE

COMMENTS: THIS CORNER IS LOCATED ± 130 SOUTH  
OF A C2 SPUR LOGGING ROAD.

IN THE PRESENCE OF: DAN McNUTT AL DVORAK

DATE: 5-24-88 PHOTO#: \_\_\_\_\_ TITLE \_\_\_\_\_

\* = County corner tag affixed.