

36  
1

TILLAMOOK COUNTY REWITNESS #337

N. 1 SEC. 36  
COR. 1 T 125 R 10 W., WM.  
S. 36

HISTORICAL: GLO Pg 14 1510 ± 1857

BK.	Pg.	MAP
4	8, 42, 90	A-117
1	97	A-100
AMA 5	62	F-26-5
SEE NOTE BIN 36 1510 FOR REFERENCING		B-631

CONDITION RLTY FOUND: SMASHED IRON PIPE

NOT FOUND	48" SPRUCE	S 110° W	27 LKS	GLO Pg 14
NOT FOUND	28" SPRUCE	N 20° E	15 LKS	GLO Pg 14
NOT FOUND	30" SPRUCE	S 2° E	54 LKS	BK. 4 Pg. 8
NOT FOUND	4" HEMLOCK	N 39° E	54° FT	BL. 4 Pg. 90
NOT FOUND	18" SPRUCE	N 57° W	43 1/2 FT	BK. 4 Pg. 90

COMMENTS:

REWITNESS

1 SET 1 1/2" IRON PIPE WITH 3" BRASS CAP IN 10" TILE & CEMENT @ POSITION OF FD. IRON PIPE

\* 60" STEEL FENCE POST WEST 15 FEET

NEW ACCESSORY:

* 24" SPRUCE	N 59° E	96 1/2'	S 36 BT CS

1/4 S 36  
S 1  
RS 287  
1979

COMMENTS: THIS CORNER IS LOCATED ± 80' WEST OF A N-S FENCE LINE @ THE SOUTH TOE OF THE NORTH DIKE ON TILLAMOOK RIVER. PIPE WAS LOCATED FROM REFERENCES SEE NOTE BIN SECTION 36 T. 125 R. 10 W..

IN THE PRESENCE OF: GALE ARTHUR & DAN McNUTT

DATE: 10-18-79 PHOTO#: 222

\* = County corner tag affixed.

TITLE