

WHOLE SEC. 3 T 2S R 9 W., WM.
 CW $\frac{1}{16}$ COR. 3 T 2S R 9 W., WM.


HISTORICAL: BK 5 Page 124
 F-23-7 2 WEA SHOWS Iron Pipe at Corner
 F-17-18 S
 F-21-10 O.S.H. SCOTT RES. ENG.
 F-40-114 W. HUDSON
 B-301 WEA 1952 Subdivision of Sec 3

CONDITION	FOUND:
GONE	1 1/2" Iron Pipe
In Position 1971	GUY POLE S84°W 173 ⁵ Δ BK 5 Pg 124
GONE	GUY POLE N 03° E 287 ²⁴ Δ BK 5 Pg 124 Pole # P29L4GR6S9
	4x4 POST 1 ⁵ EAST BK 5 Page 129

COMMENTS:

REWITNESS

I SET 2" Iron Pipe with 3" Brass Cap in 8" Tile with Cement
 * 96" Hat Section S. SOUTH = 15



NEW ACCESSORY:

Power Pole # P-29-L46-R5	N 30° W 216 ³⁰

COMMENTS: Gale and I found pipe in 1970 (gone)
 Gale Arthur and Rogar Knipple found & replaced corner
 in 1971

IN THE PRESENCE OF: Gale Arthur
 ROGAR Knipple

DATE: 1971 December PHOTO#:

* - County corner tag affixed.

TILLAMOOK COUNTY TITLE