

TILLAMOOK COUNTY REWITNESS #352

T 2 S R 9 W

SEC. 3 COR. ONLY 3 T 2 S R 9 W., WM.

HISTORICAL: MAP B-301 WE Anderson (Subdivision)

BK 1 Pg 98

BK 4 Pg 91

MAP B-516

BK 5 Pg 101


F-9-2

CONDITION	Good	FOUND:	1" Iron Pipe	field check
Now 40" Hem Stump	36" Hemlock	N80°E	2° ft	N72°E 25 ft
Now 48" Spr Stump	36" Spruce	N15°E	9° ft	N16°E 9 ft
Fd Scribing (CS 1/4 S BT) in Hemlock N80°E				
Exposed face of Spruce N15°E & Fd Scribing (S 1/4 C)				

COMMENTS:

REWITNESS

1 SET 2" Iron Pipe with Cement and 8" Tile 1971  
with Brass Cap over 1" Iron Pipe



" Hat Section "	WEST	15 ft
NEW ACCESSORY: distance to face		
18" Spruce	N07°E 66 1/2	Scribed 1/4 S3 BT CS
Face located on S.E. root flare.		

COMMENTS: The Set 2" I.P. is ± 12" High  
Corner is ± 90 feet west of gravel road.

Placed "Do Not Cut" Tag on 18" Spruce N7°E 66 1/2

IN THE PRESENCE OF: Al Duncan RS 793  
Gale Arthur  
George Urrey

DATE: 10-27-70 PHOTO: 230

County corner tag affixed. TILLAMOOK COUNTY TITLE CS.