

TILLAMOOK COUNTY REWITNESS #362

SECTION COR. SEC. $\frac{6}{7} \frac{5}{8}$ T 25 R 9 W., WM.

HISTORICAL: GLO Pg 24 MAP

Book	Page	Book	Page	MAP
10	4 & 107	4	76	F-27-8
\$3	442	1	85	F-27-7
4	64	1	9	B-215
1	89			A-1911
				A-801
				A-267


CONDITION Good FOUND: $\frac{3}{4}$ " Iron Rod

ALL BT'S GONE	Book 10 Page 4	1887	
ALL BT'S GONE	Book 10 Page 107	1893	
Fd lead Plug in Curb	Book 4 Pg 64	1950	N.W. COR. @ 13 ³⁰
Fd lead Plug in Curb	Book 4 Pg 64	1950	N.E. COR. @ 35 ³⁰
Fd post @ 53 ³⁰	F-27-8	1950	
Power Pole & Apple tree are Both missing	Book 4 Pg 64	1950	

COMMENTS:

REWITNESS

I SET $\frac{1}{4}$ " Iron Bar with 3" Brass Cap in 8" Tile & Cement



" Hat Section S. ~~W.~~ 580°W 318 feet

NEW ACCESSORY:

56 nail @ NO°W	43
56 nail @ West	51

COMMENTS: Fd $\frac{3}{4}$ " Iron Rod & Witnessed to "56" nails.

I drove the $\frac{3}{4}$ " Iron Rod down to a depth of ± 2 feet - I set Bar & Brass Cap over $\frac{3}{4}$ " Iron Rod - Cap is ± 1 " Below Pavement Surface.

IN THE PRESENCE OF GALE ARTHUR
ROGER KNIPPLE

DATE: 1-14-72

PHOTO#:

TITLE

* = County corner tag affixed.