

TILLAMOOK COUNTY REWITNESS #363
 COR. $\frac{1}{4}$ N. 8. SEC. $\frac{5}{8}$ T 25 R 9 W., WM.

HISTORICAL: GLO T25R9W Pg. 25 SET POST 1857


MAPS	
F-3-10	
E-27-7	

CONDITION Good	FOUND: 1" I.P. IN CONCRETE MAP F-3-10		
GONE	56" SPRUCE	SOUTH 105 LKS	GLO Pg. 25
GONE	64" SPRUCE	N. 58° W. 32 LKS	GLO Pg. 25

COMMENTS:

REWITNESS

1 SET $\frac{5}{8}$ " IRON ROD WITH 3" BRASS CAP INSIDE OF A FOUND 1" IRON PIPE IN A CONCRETE MONUMENT
 60" Hat Section S. ■ 10 FEET



NEW ACCESSORY:

NO NEW B.T.S AVAILABLE	

COMMENTS: THIS CORNER IS LOCATED BETWEEN THE RUNWAYS OF TILLAMOOK COUNTY AIRPORT AND ± 800' NLY OF WHERE THE RUNWAYS CROSS. THE DISTANCE TIE ON MAP F-27-7 FITS WITHIN REASON OF A FIELD TIE (± 0.8") BY C.S.!

IN THE PRESENCE OF: GALE ARTHUR, DAN McNUTT

DATE: 3-10-81

PHOTO#: _____ TITLE _____

* = County corner tag affixed.