

TILLAMOOK COUNTY REWITNESS #371
 1/4 COR. SEC. 7/8 T 2SR 9 W., WM.


HISTORICAL GLO T2SR9W Page 24
 Book 10 Page 6 Set a Post Book 53 Page 442
 Book 4 Page 76 WEA 1950 Book 1 Page 87 WEA 1950
 MAP A-598 WEA 3/4" ROD Page 100 Replaced Iron Rod with 2" Iron Pipe
 MAP A-667 SEPTEMBER 1966 ILL. Fd 24 CAST IRON PUMP HANDLE MAP A-490 WEA 1951 MAP B-424 WEA

CONDITION	FOUND:
In Position	2" IRON PIPE WITH PLUG & NAIL 4x4 Post

COMMENTS: Book 4 Page 72 - Book 4 Page 76 - Book 1 Page 87 are all the same.

REWITNESS

1 SET 2" IRON PIPE WITH BRASS CAP IN CEMENT & TILE
 * ±90 Hat Section W. 13.85 feet WEST



NEW ACCESSORY:

COMMENTS: Replaced 4x4 Post with Hat
 Section Brass Cap is FLUSH WITH PAVEMENT.

IN THE PRESENCE OF: Gale Arthur

DATE: NOVEMBER 1971

PHOTO: REC

* = County corner tag affixed.

TITLE

GW 171