

TILLAMOOK COUNTY REWITNESS #378  
 SEC.  
 COR.  $\frac{1}{4}$  9-16 T 2S R 9 W., WM.

HISTORICAL: Book 5 PAGE 136 W.C.P. 1965


Book 1 PAGE 93-1949		MAP F. 27-7
Book 4 PAGE 62-1949		GLD SET POST
Book 4 PAGE 42-1942	NOTHING	GONE 32" FIRM SSW 106 LKS = 69.96
RE/W - BIN - 1969	NOTHING	64" FIRM SSE 526 LKS = 347.6
RE/W - BK 6 Pg 463		BADLEY POTTED

CONDITION	FOUND:
FAIR	$\frac{1}{2}$ " IRON PIPE
GOOD	4x4x48" CEDAR POST 095 EAST
FAIR	NAS FENCE WEST 25' AND NORTH 25' FROM CORNER
	14" FIRM SSE 526 LKS = 347.6 BADLEY POTTED

COMMENTS:

REWITNESS

1 SET 2" IRON PIPE WITH 3" BRASS CAP IN 10" TIE FILLED WITH CEMENT  
 4" x 4" x 48" Post N.W. EAST 1.0 feet  
 " Hat Section S. E.



NEW ACCESSORY:

YELLOW COY TAG ON POST	
POWER POLE NUMBER E4-206 P29-L7	N40W 32.52

COMMENTS: CORNER IS LOCATED  $\pm$  100 FEET NORTHWEST OF BRICKYARD ROAD, AND  $\pm$  40 FEET NORTH OF SMALL CREEK WHICH RUNS WESTERLY.  
 SET 2" IP WITH 3" BRASS AT FOUND POSITION OF 1/2" IRON PIPE.

IN THE PRESENCE OF: GALE ARTHUR - DAN MCNUIT

DATE: 3-74 PHOTO#: \_\_\_\_\_

\* = County corner tag affixed.

TITLE \_\_\_\_\_